

NOTICE TO MARINERS



012 of 2023

Issued by Townsville Maritime Region on 10 January 2023

Area: North Queensland
Locality: Halifax Bay
Activity: Obstruction, North cardinal mark buoy established

Mariners are advised that:

Yabulu refinery submerged pipe outfall isolated danger beacon in position latitude 19°09.2268'S; longitude 146°38.2001'E has been discontinued and removed.

The temporary special mark buoy Fl Y 2.5s in position latitude 19°09.225'S; longitude 146°38.207'E has been replaced by a north cardinal mark buoy QW in position latitude 19°09.227'S; longitude 146°38.200'E to warn mariners of the submerged pipe outfall and associated obstruction.

Mariners are advised to navigate in the area with caution.

Refer to notice:
Cancel notice: 008(T) of 2023

AUS charts affected: 256, 827

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA94 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office;
Phone 07 4421 8100 Email: vtstowns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland