Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



374 of 2024

Issued by Townsville Maritime Region on 25 July 2024

Area: Townsville pilotage area

Locality: Ross Creek, Townsville

Activity: Port Lateral mark no 6 altered.

Mariners are advised that:

Ross Creek Port lateral marker buoy No 6 has been withdrawn and permanently replaced with a Port Lateral beacon RC 6 with light characteristics Fl.R 3s and day shape in position Latitude 19°15.4610'S, Longitude 146° 49.5360'E.

Mariners are advised to navigate with caution.

Refer to notice: none Cancel notice: none

AUS charts affected: AUS256, AUS827 ENC Cells affected: AU5TSV01, AU420146

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100 Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland