## 9. Tugs

## 9.1 Tug information

Two tugs are operated by Cape Flattery Silica Mine to service scheduled shipping for the mine.

All vessels require 2 tugs for berthing and unberthing.

The use of workboats to assist with berthing and unberthing is no longer accepted.