

NOTICE TO MARINERS



391 (T) of 2024

Issued by Cairns Maritime Region on 31 July 2024

Area: Karumba pilotage area
Locality: Karumba Channel – Elbow Bank
Activity: EB1 buoy altered in position

Mariners are advised that:

EB1 starboard lateral buoy has been altered in position. Approximate position of the buoy is latitude 17° 26.421' S, longitude 140° 44.590' E. Lighting characteristics have not changed.

Mariners are to navigate with caution.

Refer to notice: 272(T) of 2024

Cancel notice: 272(T) of 2024

AUS charts affected: AUS 6 and 303

ENC Cells affected: AU5006PO and AU418140

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland