Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



150 of 2024

Issued by Brisbane Maritime Region on 2 April 2024

Area: Southport pilotage area

Locality: Southern Broadwater, off Southport

Activity: aid to navigation altered

Mariners are advised that:

The unlit starboard lateral mark buoy in position latitude 27°57.8721′ S, longitude 153°25.1525′ E, located adjacent to the Broadwater Parklands, has been altered to an unlit special mark buoy to mark the southern most point of the small craft channel.

Refer to notice: none Cancel notice: none

AUS charts affected: 814

ENC Cells affected: AU5GOC01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500 Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland