

NOTICE TO MARINERS

149 of 2024

Issued by Brisbane Maritime Region on 2 April 2024

Area: Southport pilotage area

Locality: Southern Broadwater, off Southport

Activity: aids to navigation permanently withdrawn from service

Mariners are advised that:

The following aids to navigation, located in the small craft channel adjacent to the Broadwater Parklands, have been permanently withdrawn from service: -

- Unlit special mark buoy in position latitude 27°57.9275' S, longitude 153°25.2147' E.
- Unlit starboard lateral mark buoy in position latitude 27°58.2320' S, longitude 153°25.2828' E.
- Unlit starboard lateral mark buoy in position latitude 27°58.1440' S, longitude 153°25.2325' E.
- Unlit starboard lateral mark buoy in position latitude 27°58.0417' S, longitude 153°25.1996' E.
- Unlit starboard lateral mark buoy in position latitude 27°57.9571' S, longitude 153°25.2250' E.
- Unlit port lateral mark buoy in position latitude 27°57.9250' S, longitude 153°25.2035' E.

Refer to notice: none

Cancel notice: none

AUS charts affected: 814

ENC Cells affected: AU5GOC01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland