



REGISTERED N<sup>o</sup> 37/4244 L.S.G.

IN ANY FURTHER CORRESPONDENCE  
ON THIS SUBJECT THE ABOVE N<sup>o</sup> & DATE  
SHOULD BE QUOTED.

PLEASE ADDRESS  
SURVEYOR-GENERAL,  
BOX 641 J.G.P.O.,  
BRISBANE.



Survey Office  
Department of Public Lands,

*Brisbane* 14th October, 1937.

Memorandum to Mr. Staff Surveyor H.D. Mellor.

-----0-----

The Inspecting Engineer of the Public Estates Improvement Branch reports that bush stick finders rot out in a very short time and cause delay in finding the centre line where jungle vines have a tendency to rapid growth.

In the circumstances, it is desired that painted split finders only be used in jungle country.

Surveyor-General.