Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



578 of 2023

Issued by Cairns Maritime Region on 5 December 2023

Area: Far North Queensland

Locality: Saibai Island

Activity: Port Lateral mark established

Mariners are advised that:

A port lateral marker buoy has been established mid-way along the approach channel. A red port lateral marker buoy, light characteristics FI R 2.5s has been established in approximate position Latitude 09° 22.623' S, Longitude 142° 36.722' E.

Mariners are to navigate with caution.

Refer to notice: none Cancel notice: none

AUS charts affected: AUS 841

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400 Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland