## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 145 (T) of 2024

Issued by Gladstone Maritime Region on 28 March 2024

**Area:** Maryborough pilotage area

**Locality:** South White Cliffs, Great Sandy Strait

Activity: Navigation Aid replaced

## Mariners are advised that:

South White Cliffs 2 port lateral beacon with light characteristic FI(R) 2.5s has been destroyed. The beacon has been replaced temporarily with a port lateral buoy with the same light characteristic in approximate position 25° 30.854′S 152° 58.863′E.

Refer to notice: none

Cancel notice: 619(T) of 2023

AUS charts affected: 817 ENC Cells affected: AU426152

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208 Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland