

NOTICE TO MARINERS



010 (T) of 2024

Issued by Gladstone Maritime Region on 4 January 2024

Area: Maryborough pilotage area

Locality: Great Sandy Strait

Activity: Aid to Navigation missing

Mariners are advised that:

Special Mark B1 with light characteristic Fl(Y) 3s in position 25° 20.9805'S, 153° 02.3373'E is missing. A temporary buoy has been established in position with the same light characteristic in approximate position 25° 20.987'S 153° 02.341'E . The beacon is expected to be replaced by Wednesday, 31 January 2024.

Mariners are advised to navigate with caution in the area.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS817

ENC Cells affected: AU426152, AU426153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland