

# NOTICE TO MARINERS



## 587 of 2024

---

Issued by Gladstone Maritime Region on 2 December 2024

**Area:** Maryborough pilotage area  
**Locality:** Great Sandy Strait  
**Activity:** change from beacon to buoy for S35 and S39.

Mariners are advised that:

Maritime Safety Queensland has replaced existing starboard lateral beacons 'S35 and S39' with buoys. The buoys have been established in new positions as follows:

**S35** – Starboard lateral buoy  
Latitude 25° 39.261' S, longitude 152° 58.144' E

**S39** - Starboard lateral buoy  
Latitude 25° 40.321' S longitude 152° 58.548' E

The starboard lateral buoys remain lit –

**S35** - Fl (G) 4.0s. 0.5 + 3.5

**S39** – Fl (G) 6.0s. 1.0 + 5.0

**Refer to notice:**

**Cancel notice:**

**AUS charts affected:** AUS817

**ENC Cells affected:** AU26152

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: [vtsgladstone@msq.qld.gov.au](mailto:vtsgladstone@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Gladstone) - Maritime Safety Queensland