

# NOTICE TO MARINERS

## 107 of 2025

---

Issued by Gladstone Maritime Region on 24 March 2025

**Area:** Maryborough pilotage area

**Locality:** Burrum Heads

**Activity:** Permanent change of Aid to Navigation characteristic

Mariners are advised that:

Maritime Safety Queensland has replaced existing unlit port lateral beacon 'Burrum 12' with an unlit port lateral buoy.

The buoy has been established in a new approximate position as follows:

**Burrum 12** - Port Lateral Buoy

Latitude 25° 10.913' S Longitude 152° 37.188' E

**Refer to notice:** none

**Cancel notice:** 087(T) of 2025

**AUS charts affected:** AUS 817

**ENC Cells affected:** AU426152

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: [vtsgladstone@msq.qld.gov.au](mailto:vtsgladstone@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Gladstone) - Maritime Safety Queensland