## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 526 of 2024

Issued by Gladstone Maritime Region on 24 October 2024

- Area: Maryborough pilotage area
- Locality: Great Sandy Strait
- Activity: Permanent change of Aid to Navigation characteristic

Mariners are advised that:

Port Lateral beacon S8 has been replaced with a buoy

The buoy has been established in a new position as follows:

**S8** – Port Lateral Buoy Latitude 25° 14.311' S Longitude 152° 57.801' E

The Port Lateral Buoy remains lit – Fl (R) 2.5s. 0.5 + 2.0

Refer to notice: Cancel notice:

AUS charts affected: AUS817 ENC Cells affected: AU426152

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland