

# NOTICE TO MARINERS



## 525 of 2024

---

Issued by Gladstone Maritime Region on 23 October 2024

**Area:** Maryborough pilotage area  
**Locality:** South White Cliffs, Great Sandy Strait  
**Activity:** Permanent change of Aid to Navigation characteristic

Mariners are advised that:

Maritime Safety Queensland has replaced existing port lateral beacon 'South White Cliffs 2' with a port lateral buoy. The buoy has been established in a new position as follows:

**South White Cliffs 2 – Port Lateral Buoy**  
Latitude 25° 30.854' S Longitude 152° 58.863' E

The Port Lateral buoy remains lit – Fl (R) 2.5s.  
0.5 + 2.0

**Refer to notice:**  
**Cancel notice:** 145 (T) of 2024

**AUS charts affected:** 817  
**ENC Cells affected:** AU426152

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Gladstone Regional Harbour Master's office:  
Phone 07 4839 0208      Email: vtsgladstone@msq.qld.gov.au

**Notice authorised by:** Regional Harbour Master (Gladstone) - Maritime Safety Queensland