



NOTICE TO MARINERS

051 (T) of 2025

Issued by Townsville Maritime Region on 19 February 2025

Area: North Queensland
Locality: Oyster Point, Cardwell
Activity: Obstruction, Special Mark Established

Mariners are advised that:

A special mark buoy FL.Y.2.5 has been established in position Latitude 18°16.224'S Longitude 146°02.677'E. The buoy marks an obstruction caused by a submerged vessel located near Oyster Point, Cardwell.

Mariners are advised to navigate the area with caution.

Refer to notice: 032T of 2025

Cancel notice: 032T of 2025

AUS charts affected: AUS 258, AUS 259

ENC Cells affected: AU419146,

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland