

NOTICE TO MARINERS

280 of 2024

Issued by Townsville Maritime Region on 7 June 2024

Area: North Queensland
Locality: Enterprise Channel, Dungeness, Lucinda
Activity: Special mark withdrawn, Speed Buoys established

Mariners are advised that:

The following Special Mark buoys have been permanently withdrawn.

Latitude 18° 31.268'S, Longitude 146° 18.937'E, FL Y 2.5s

Latitude 18° 31.837'S, Longitude 146° 18.748'E, FL Y 2.5s

Buoys informing mariners of the “6 Knots” gazetted speed limit have been established in the following positions.

Latitude	Longitude	Sequence	Characteristics
18° 31.268'E	146° 18.937'E	FL Y 2.5s	White buoy “6 Knots”
18° 31.395'S	146° 18.984'E	FL Y 2.5s	
18° 31.837'S	146° 18.748'E	FL Y 2.5s	

Mariners are advised to navigate with caution.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS256, AUS826

ENC Cells affected: AU5TSV01, AU420146

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master’s office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland