## NOTICE TO MARINERS



## 349 of 2024

Issued by Brisbane Maritime Region on 12 July 2024

- Area: Brisbane pilotage area
- Locality: Rous Channel
- Activity: Aid to navigation altered in position

Mariners are advised that:

Rous channel 4, a port lateral buoy displaying the light characteristic Fl R 2.5s in approximate position latitude 27°22.337'S, longitude 153°24.676'E has been altered in position to approximate position latitude 27°24.551'S, longitude 153°21.116'E.

Rous Channel 9, a starboard lateral buoy displaying the light characteristic Fl G 4.0s in approximate position latitude 27°23.079'S, longitude 153°23.958'E has been altered in position to approximate position latitude 27°24.030'S, longitude 153°23.230'E.

Mariners are advised to navigate with caution when transiting the area.

Refer to notice: none Cancel notice: none

AUS charts affected: AUS236 ENC Cells affected: AU428153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland