

NOTICE TO MARINERS



568 (T) of 2024

Issued by Brisbane Maritime Region on 18 November 2024

Area: Brisbane pilotage area
Locality: Maroom Bank, Moreton Bay
Activity: Aid to navigation unlit

Mariners are advised that:

Maroom Bank, a starboard lateral beacon displaying the light characteristic Fl.G.6s in approximate position latitude 27°27.067'S, longitude 153°19.620'E has been reported and confirmed as unlit.

The lantern is expected to be repaired by 29 November 2024.

Mariners are advised to navigate with caution when transiting the area.

Refer to notice: none
Cancel notice: none

AUS charts affected: AUS814
ENC Cells affected: AU5BNE01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland