

# NOTICE TO MARINERS



## 371 of 2024

---

Issued by Brisbane Maritime Region on 24 July 2024

**Area:** Brisbane pilotage area  
**Locality:** Rous Channel  
**Activity:** Aid to navigation altered in position.

Mariners are advised that:

Rous Channel 10, a port lateral buoy displaying the light characteristic Fl R 4s in approximate position latitude 27°22.742'S, longitude 153°23.658'E has been altered in position to approximate position latitude 27°23.834'S, longitude 153°24.442'E.

Rous Channel 8, a port lateral buoy displaying the light characteristic Fl R 1.5s in approximate position latitude 27°22.474'S, longitude 153°23.838'E has been altered in position to approximate position latitude 27°24.175'S, longitude 153°23.340'E.

Rous Channel 12, a port lateral buoy displaying the light characteristic Fl R 2.5s in approximate position latitude 27°24.371'S, longitude 153°23.198'E has been altered in position to approximate position latitude 27°24.693'S, longitude 153°22.426'E.

Mariners are advised to navigate with caution when transiting the area.

**Refer to notice:** none  
**Cancel notice:** none

**AUS charts affected:** AUS236  
**ENC Cells affected:** AU428153

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: [vtsbrisbane@msq.qld.gov.au](mailto:vtsbrisbane@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Brisbane) - Maritime Safety Queensland