

# NOTICE TO MARINERS



## 378 of 2024

---

Issued by Brisbane Maritime Region on 26 July 2024

**Area:** Brisbane pilotage area  
**Locality:** Rous Channel  
**Activity:** Aid to navigation altered in position

Mariners are advised that:

Rous Channel 3, a starboard lateral buoy displaying the light characteristic Fl G 4s in approximate position latitude 27°23.391'S, longitude 153°24.981'E has been altered in position to approximate position latitude 27°23.235'S, longitude 153°25.476'E.

Rous Channel 18, a port lateral buoy displaying the light characteristic Fl R 2.5s in approximate position latitude 27°23.595'S, longitude 153°24.995'E has been altered in position to approximate position latitude 27°23.362'S, longitude 153°25.407'E

Rous Channel 19, a starboard lateral buoy displaying the light characteristic Fl G 2.5s in approximate position latitude 27°23.647'S, longitude 153°24.706'E has been altered in position to approximate position latitude 27°23.698'S, longitude 153°24.531'E

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** AUS236

**ENC Cells affected:** AU428153

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: [vtsbrisbane@msq.qld.gov.au](mailto:vtsbrisbane@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Brisbane) - Maritime Safety Queensland