



# NOTICE TO MARINERS

## 126 of 2025

---

Issued by Brisbane Maritime Region on 4 April 2025

**Area:** Brisbane pilotage area  
**Locality:** Canaipa Passage, Moreton Bay  
**Activity:** Navigation Aid altered in Position

Mariners are advised that:

Canaipa South 10, a Port lateral beacon displaying the light characteristic Fl R 2.5s that was previously located in approximate position latitude 27° 42.174' S, longitude 153° 23.783' E has been altered in position to approximate position latitude 27° 42.173' S, longitude 153° 23.769' E.

Mariners are advised to navigate with caution in the area.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** AUS814

**ENC Cells affected:** AU428153

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: [vtsbrisbane@msq.qld.gov.au](mailto:vtsbrisbane@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Brisbane) - Maritime Safety Queensland