

# NOTICE TO MARINERS



## 037 of 2025

---

Issued by Brisbane Maritime Region on 6 February 2025

**Area:** Brisbane pilotage area  
**Locality:** Pumicestone Passage  
**Activity:** Aid to navigation removed

Mariners are advised that:

The following beacons have been permanently removed

Port lateral beacon FL 2.5s Pumicestone passage Gallagher 2 in position Latitude  $-27^{\circ}02.120'$  South  
Longitude  $153^{\circ}05.701'$  East

Port lateral beacon Pumicestone Passage Banksia 2 in position Latitude  $27^{\circ}02.310'$  South Longitude  
 $153^{\circ}07.76'$  East

Mariners are advised to navigate with caution when transiting the area.

**Refer to notice:** none  
**Cancel notice:** none

**AUS charts affected:** AUS236 AUS4060 AUS4602 AUS815  
**ENC Cells affected:** AU5BNE02 AU130150 AU230150 AU230150 AU428153

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: [vtsbrisbane@msq.qld.gov.au](mailto:vtsbrisbane@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Brisbane) - Maritime Safety Queensland