

NOTICE TO MARINERS



059 (T) of 2025

Issued by Townsville Maritime Region on 25 February 2025

Area: Abbot Point and Bowen pilotage areas
Locality: Port Denison, Bowen
Activity: Starboard lateral mark buoy M5 missing.

Mariners are advised that:

Mariners are advised that the starboard lateral mark buoy "M5" Fl.G 4s in position latitude 20°02.350' S, longitude 148°15.775' E is reported off station.

Mariners are advised to navigate with caution whilst transiting the area.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS268,825,826

ENC Cells affected: AU5268P1, AU320148

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland