

NOTICE TO MARINERS



004 (T) of 2025

Issued by Gladstone Maritime Region on 6 January 2025

Area: Gladstone pilotage area
Locality: South Channel
Activity: Beacon S1 not in position – Replaced with a buoy

Mariners are advised that:

the starboard lateral mark beacon S1 previously located at position: 23° 53.922'S, 151° 30.395'E has been reported as missing. The beacon is no longer in its charted position and a temporary lit buoy has been established in position. Mariners are to navigate with extreme caution around this location.

Refer to notice: none
Cancel notice: 602(t) of 2024

AUS charts affected: AUS246
ENC Cells affected: AU5GLT01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:
Phone 07 4839 0208 Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland