

NOTICE TO MARINERS



098 (T) of 2025

Issued by Gladstone Maritime Region on 18 March 2025

Area: Gladstone pilotage area
Locality: South Channel
Activity: S1 beacon replaced with a buoy

Mariners are advised that:

the starboard lateral beacon S1, located at position: 23° 53.922'S, 151° 30.395'E has been destroyed. The beacon has been replaced by a temporary buoy which has been placed in the beacons charted position, displaying the same characteristics. Due to the mooring arrangement and depth of water, the location of the buoy can change slightly due to weather and tidal conditions. Mariners are requested to navigate this area with caution.

Refer to notice: none

Cancel notice: 004(t) of 2025

AUS charts affected: AUS246

ENC Cells affected: AU5GLT01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland