



ADVICE

Issued by Cairns Maritime Region on 11 December 2024

Area: Thursday Island pilotage area
Locality: Bertie Bay Goods Island
Activity: Permanent removal swing mooring buoy CT-034.

Mariners are advised that:

The mooring buoy (FL Y 4s) has been removed permanently from GPS position
10°43.2S 142°10E

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland