Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



283 of 2024

Issued by Townsville Maritime Region on 7 June 2024

Area: Townsville pilotage area

Locality: Horseshoe Bay, Magnetic Island

Activity: Special marks withdrawn, Speed Buoys Established

Mariners are advised that:

Buoys informing mariners of the "6 knots" gazetted speed limit have been established in the following positions as shown on the attached map S11-695 Horseshoe Bay 6 knots speed limits.

Latitude	Longitude	Sequence	Characteristics
19° 6.330'S	146° 51.645′E	FL Y 4.0s	
19° 6.435'S	146° 51.592'E	FL Y 4.0s	White buoy "6 Knots"
19° 6.588'S	146° 51.511'E	FL Y 4.0s	
19° 6.841'S	146° 51.450'E	FL Y 4.0s	
19° 6.940'S	146° 51.510'E	FL Y 4.0s	

The following special mark buoys have been permanently withdrawn:

Latitude	Longitude	Sequence
19° 6.340'S	146° 51.659'E	FL Y 4.0s
19° 6.841'S	146° 51.450'E	FL Y 4.0s
19° 6.940'S	146° 51.520'E	FL Y 4.0s

Mariners are advised to navigate with caution.

Refer to notice: none Cancel notice: none

AUS charts affected: AUS256, AUS827 ENC Cells affected: AU5TSV01, AU420146

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100 Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland



Horizontal datum: GDA2020 Projection: UTM (MGA Zone 55)

Prepared 6 June 2024 Maritime Safety Queensland Port Operations and VTS - Spatial Services 6 KNOT SPEED LIMIT - HORSESHOE BAY
MAGNETIC ISLAND - TOWNSVILLE

