Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



070 (T) of 2025

Issued by Townsville Maritime Region on 5 March 2025

Area: Townsville pilotage area

Locality: Townsville approach channels, harbours and berths

Activity: amended port navigation depths

Mariners are advised that the design and actual berth depths below port datum, Lowest Astronomical Tide, are amended, as of Wednesday, 5 March 2025, as follows:

| | Actual Depths (metres) | Remarks |
|-----------------------------------|---------------------------|-------------------------|
| Outer Harbour (Arrival Channel) | 8.2* | |
| Outer Harbour (Departure Channel) | 11.5* | |
| Sea Channel | 12.1* | |
| Platypus Channel | 11.8 | |
| Inner Harbour | 11.9 | |
| No. 1 Berth Pocket | 13.0* | |
| No. 2 Berth Pocket | 10.3 | |
| No. 3 Berth Pocket | 11.4* | |
| No. 4 Berth Pocket | 12.2 | |
| No. 8 Berth Pocket | 12.0 | |
| No. 9 Berth Pocket | 12.0 | |
| No. 10 Berth Pocket | 11.4 | |
| No. 11 Berth Pocket | 10.9* | Berth marks 10m to 260m |
| No. 11 Berth Pocket | 10.9* | Berth marks 0m to 10m |
| Ross River Channel | 1.7* | Entrance to Beacon No.6 |
| | | |

*Revised entry

Refer to notice: 605(T) of 2024, **Cancel notice:** 605 (T) of 2024

AUS charts affected: AUS256 ENC Cells affected: AU6TSV01, AU6TSV02, AU6TSV03, AU6TSV04; AU5TSV01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100 E

Email: vtstownsville@msq.qld.gov.au