Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



506 (T) of 2023

Issued by Cairns Maritime Region on 13 November 2023

Area: Karumba pilotage area

Locality: Karumba

Activity: Deployment of two all waters FADs

Mariners are advised that:

Two all water FADs have been deployed off Karumba in the following positions:

FAD G6 (offshore site 17nm from Karumba):

Surface FAD - 17°14.916'S 140°37.286'E Yellow Special Mark Buoy Y FL Y 3S

Subsurface FAD - $17^{\circ}14.836'$ S $140^{\circ}37.281'$ E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°14.885'S 140°37.381'E subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°14.989'S 140°37.294'E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°14.904'S 140°37.198'E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°14.841'S 140°37.234'E (subsurface buoy 4m below surface at LAT)

FAD G5 (Inshore site 8nm from Karumba)

Surface FAD - 17°21.737'S 140°43.887'E Yellow Special Mark Buoy Y FL Y 3S

Subsurface FAD - 17°21.672'S 140°43.890'E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°21.733'S 140°43.946'E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°21.787'S 140°43.902'E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°21.714'S 140°43.845'E (subsurface buoy 4m below surface at LAT)

Subsurface FAD - 17°21.692'S 140°43.911'E (subsurface buoy 4m below surface at LAT)

Mariners are to navigate with caution.

Refer to notice: none Cancel notice: none

AUS charts affected: 303, 06

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400 Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland