

NOTICE TO MARINERS

569 of 2024

Issued by Brisbane Maritime Region on 19 November 2024

Area: Southport pilotage area
Locality: Coomera River – South Branch
Activity: Channel repositioning

Mariners are advised that:

Repositioning of buoys has been undertaken to support safe vessel movements in the South branch of the Coomera River. The following movements have occurred:

Withdrawn Port lateral buoy
Fl R 2.5s
Latitude 27°52.613
Longitude 153°23.159

Reposition Port lateral buoy
Fl R 1.5s
Old position New position
Latitude 27°52.630 Latitude 27°52.630
Longitude 153°23.358 Longitude 153°23.365

Reposition Port lateral buoy
Fl R 3.0s
Old position New position
Latitude 27°52.628 Latitude 27°52.631
Longitude 153°23.275 Longitude 153°23.291

Mariners should navigate the area with caution.

Refer to notice: none
Cancel notice: none

AUS charts affected: AUS814
ENC Cells affected: AU428153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: **Regional Harbour Master (Brisbane) - Maritime Safety Queensland**