## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 585 of 2024

Issued by Cairns Maritime Region on 29 November 2024

**Area:** Far North Queensland

Locality: Badu Island

**Activity:** Aids to Navigation buoys established.

Mariners are advised that:

The below aids to navigation have been established in the Badu Island region.

A north cardinal buoy has been established in approximate position latitude 10° 11.542'S, longitude 142° 07.849'E and displays light characteristics Q1s.

A south cardinal buoy has been established in approximate position latitude 10° 11.250′S, longitude  $142^{\circ}08.976′E$  and displays light characteristics Q(6) + LFL 15s.

A special mark buoy has been established in approximate position latitude 10° 11.174'S, longitude 142° 09.529'E and displays light characteristics Fl Y 4s.

Mariners are to navigate with caution.

Refer to notice: none Cancel notice: none

AUS charts affected: Aus 841 ENC Cells affected: Au411142

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400 Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland