

ADVICE

Issued by Brisbane Maritime Region on 19 April 2022

Area: Brisbane pilotage area
Locality: Brisbane River
Activity: Post-2022 Flood - Submerged Objects

Mariners are advised that:

Following hydrographic surveys of the Brisbane River, Entrance Beacons to Eleanor Schonell Bridge, a number of submerged objects remain. Attached maps s11-576a, s11-576b and s11-576c provide an overview of specific locations.

These objects may pose a hazard to navigation when anchoring, trawling and during other sub-surface activities in these areas. Unusual currents may also exist in the area. Mariners should navigate with due caution when operating in close proximity to these locations.

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA94 datum.

For further information about this notice, please contact:


The Brisbane Regional Harbour Master's office:
Phone 07 3632 7500 Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland

LEGEND

 Approximate extent of submerged flood debris.

Mariners are advised that the debris areas are concentrated in the outer thirds of the waterway. Known submerged hazards adjacent to the banks have been found by survey March/April 2022. The hazards can move. Navigate carefully.



To be used with appropriate NTM
© The State of Queensland 2022
(Transport and Main Roads)



Prepared 13 April 2022
Maritime Safety Queensland
Spatial Services

QUEENSLAND NOTICE TO MARINERS
Issued by Maritime Safety Queensland
SUBMERGED FLOOD DEBRIS ADVICE
ENTRANCE CHANNEL TO LYTTON
2022 BRISBANE RIVER FLOOD

QNTM updates also available
from www.msq.qld.gov.au
Datum: GDA94 horizontal. LAT vertical
Map projection: UTM (MGA zone 56)

Map S11- 576a





**Queensland
Government**

LEGEND

 Approximate extent of submerged flood debris.

Mariners are advised that the debris areas are concentrated in the outer thirds of the waterway. Known submerged hazards adjacent to the banks have been found by survey March/April 2022. The hazards can move. Navigate carefully.



To be used with appropriate NTM
© The State of Queensland 2022
(Transport and Main Roads)



Prepared 13 April 2022
Maritime Safety Queensland
Spatial Services

QUEENSLAND NOTICE TO MARINERS
Issued by Maritime Safety Queensland
SUBMERGED FLOOD DEBRIS ADVICE
LYTTON TO HAMILTON
2022 BRISBANE RIVER FLOOD

QNTM updates also available
from www.msq.qld.gov.au
Datum: GDA94 horizontal. LAT vertical
Map projection: UTM (MGA zone 56)

Map S11- 576b





Queensland
Government

LEGEND

 Approximate extent of submerged flood debris.

Mariners are advised that the debris areas are concentrated in the outer thirds of the waterway. Known submerged hazards adjacent to the banks have been found by survey March/April 2022. The hazards can move. Navigate carefully.



To be used with appropriate NTM
© The State of Queensland 2022
(Transport and Main Roads)



Prepared 13 April 2022
Maritime Safety Queensland
Spatial Services

QUEENSLAND NOTICE TO MARINERS
Issued by Maritime Safety Queensland
SUBMERGED FLOOD DEBRIS ADVICE
HAMILTON TO ST LUCIA
2022 BRISBANE RIVER FLOOD

QNTM updates also available
from www.msq.qld.gov.au
Datum: GDA94 horizontal. LAT vertical
Map projection: UTM (MGA zone 56)

Map S11- 576c

