

NOTICE TO MARINERS



564 of 2024

Issued by Cairns Maritime Region on 14 November 2024

Area: Weipa pilotage area
Locality: Lorim Point - Weipa Harbour
Activity: Lorim Point lead lights permanently discontinued

Mariners are advised that:

The Lorim Point front and rear berthing / clearance lead lights in the below positions have been permanently discontinued.

- Front berthing / clearance lead light – Latitude 12° 39.8119'S, Longitude 141° 51.0290'E
- Rear berthing / clearance lead light – Latitude 12° 39.7391'S, Longitude 141° 50.8996'E

Mariners should navigate the area with caution.

Refer to notice: none
Cancel notice: none

AUS charts affected: AUS 4
ENC Cells affected: AU413141, AU5004P1

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:
Phone 07 4052 7400 Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland