## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 039 of 2024

## Issued by Gladstone Maritime Region on 19 January 2024

- Area: Maryborough pilotage area
- Locality: Beelbi Creek, Toogoom
- Activity: Changes to existing AtoN characteristics and new positions

Mariners are advised that:

Maritime Safety Queensland has removed existing starboard lateral beacons in Beelbi Creek and established starboard lateral buoys in new positions. Aids to navigation in the creek are not lit and the new approximate positions are as follows:

**Toogoom 1** – Starboard Lateral Buoy latitude 25° 14.237' S longitude 152° 40.295' E

**Toogoom 3** - Starboard Lateral Buoy latitude 25° 14.716' S longitude 152° 40.057' E

Sand shoaling in Beelbi Creek is rapidly changing and mariners are advised to seek local knowledge and navigate the area with caution.

Refer to notice: Cancel notice: 011 (T) of 2024

AUS charts affected: 817 ENC Cells affected: AU26152

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208 Em

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland