## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 239 of 2024

Issued by Gladstone Maritime Region on 14 May 2024

**Area:** Maryborough pilotage area

**Locality:** southeast of Urangan Boat Harbour

Activity: spar buoy permanently withdrawn

Mariners are advised that:

The white spar buoy in approximate position 25° 17.893' S, 152° 55.012'E has been permanently withdrawn.

Refer to notice: none Cancel notice: none

AUS charts affected: 817

ENC Cells affected: AU426152

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208 Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland