## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 096 of 2025

## Issued by Gladstone Maritime Region on 17 March 2025

- Area: Maryborough pilotage area
- Locality: Tin Can Bay Inlet
- Activity: Establishment of Special mark

Mariners are advised that:

A Special mark has been established in the Tin Can Bay Inlet. The Special Mark is lit by a yellow flashing light identifiable by the following characteristics Fl Y 3.0 (0.3 sec on, 2.7 sec off).

	Latitude	Longitude
Teebar Creek 2 Special Mark	25°51.5497′S	153°02.1689′E

**Refer to notice:** none **Cancel notice:** 540(T) of 2023

AUS charts affected: AUS815, AUS817 ENC Cells affected: AU426153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland