16. Appendices

<u>16.1</u>	Pilot Transfer Arrangements – Marine Notice 04/2023	61
<u>16.2</u>	VTS Vessel Booking Application Form	72
<u>16.3</u>	Dangerous Cargo Report (Form 3217)	73
<u>16.4</u>	Dangerous Cargo Event Report (Form 3220)	75
<u>16.5</u>	Arrival/Departure Report (Form 3452)	76
<u>16.6</u>	Bundaberg port layout	78
<u>16.7</u>	Bundaberg Pilot Boarding Ground	79
<u>16.8</u>	Pilot ladder boarding arrangement	80
<u>16.9</u>	Requirements for pilotage exemption	81
<u>16.10</u>	<u>Pilotage Passage Plan</u>	83
<u>16.11</u>	Marine Pollution Report (Form 3968)	85
<u>16.12</u>	Marine Incident report (Form 3071)	86
<u>16.13</u>	Defects report form AMSA 355	90
16.14	Gas-Free Status Declaration	91
<u>16.15</u>	Bundaberg Port and Pilotage Areas	92
16.16	Example – Permission to Immobilise Main Engines	93
16.17	Small craft ship navigation areas and recommended courses	94
16.18	Cyclone tracking chartlet – eastern Australia	95
16.19	Pilot Ladder Checklist	96
16.20	Safe Work Method Statement – Boarding by ladder	100
16.8	Pilot ladder boarding arrangement	80
16.9	Requirements for pilotage exemption	81
16.10	Pilotage Passage Plan	83
16.11	Marine Pollution Report (Form 3968)	85
16.12	Marine Incident report (Form 3071)	86
16.13	Defects report form AMSA 355	90
16.14	Gas-Free Status Declaration	91
16.15	Bundaberg Port and Pilotage Areas	92
16.16	Example – Permission to Immobilise Main Engines	93
16.17	Small craft ship navigation areas and recommended courses	94
16.18	Cyclone tracking chartlet – eastern Australia	95
16.19	Pilot Ladder Checklist	96
16.20	Safe Work Method Statement – Boarding by ladder	100

16.1 Pilot Transfer Arrangements – Marine Notice 04/2023



MARINE NOTICE

Marine Notice 2023/04 Supersedes 2022/03

Pilot transfer arrangements

Purpose

This Marine Notice reminds ship owners, operators, masters, crews, recognised organisations, marine pilots and pilotage providers about their obligation to provide and ensure continued safe pilot transfer arrangements on ships.

Background

Since November 2017 several pilots' lives were placed at risk, in multiple separate incidents where a man rope parted, or its securing point failed. Additionally, AMSA received several incident reports on safety issues related to pilot transfer arrangements.

Ship owners, operators, masters and crews are reminded that pilot transfer arrangements, including pilot ladders, must comply with <u>Marine Order 21</u> (Safety and emergency arrangements) 2016 (<u>MO21</u>) which sets out Australia's obligations under the International Convention for the Safety of Life at Sea (SOLAS) Chapter V Regulation 23 (SOLAS V/23).

Pilot transfer arrangement standards

Whenever a pilot or other person embarks or disembarks from a ship by ladder, they entrust their safety to the pilot transfer arrangements provided by the ship and the pilot boat crew.

SOLAS V/23 sets out the minimum standards for pilot transfer arrangements on ships on or after 1 July 2012. The International Maritime Organisation (IMO) standards related to pilot transfer arrangements are found in:

- IMO Resolution A.1045(27) Pilot transfer arrangements.
- IMO Resolution A.1108(29) Amendments to the Recommendations on Pilot Transfer Arrangements (Resolution A.1045(27)).
- MSC.1/Circ. 1428 Pilot Transfer Arrangements Required boarding arrangements for pilots
- MSC.1/Circ.1495/Rev.1. Unified Interpretation of SOLAS Regulation V/23.3.3 on Pilot Transfer Arrangements

SOLAS V/23.2.3 also states a pilot ladder shall be certified by the manufacturer as complying with SOLAS V/23 or "with an international standard acceptable to the Organization" and refers to ISO 799-1:2019 "Ships and marine technology – pilot ladders". Compliance with this particular provision of SOLAS V/23 can be met when a manufacturer has certified the pilot ladder complies with either of the IMO or ISO standards, noting they are not identical.

Where a pilot ladder has been certified under the ISO standard, AMSA expects that the ladder is strength tested according to the standard. Where this test has not been conducted within 30 months, the ladder should not be used until the test is conducted, or the ladder is replaced.

When purchasing a pilot ladder, care should be exercised that the product supplied actually meets the above requirements - relying on the manufacturer's documentation may not be sufficient in some cases. If in doubt, the ship's Recognised Organisation should be requested to confirm that the ladder meets the minimum standards.

Internet address for all current marine notices: www.amsa.gov.au

Page 1 of 11

Pilot transfer arrangements

IMO Circular MSC.1/Circ.1428 illustrates the pilot transfer arrangements required by SOLAS V/23.

When using a combination pilot ladder arrangement, the pilot ladder and accommodation ladder are required to be secured to the ship's side. A common means of securing both the pilot ladder and accommodation ladders is with magnetic pads (refer to photo 1 below as an example).



Photo 1: Example of securing both the pilot ladder and accommodation ladders with magnetic pads (Reproduced with permission from Fremantle Ports).

Clear and efficient communication with the pilot boat master is essential to ensure the safety of the pilot transfer arrangements before a person uses the ladder. The pilot boat master is best positioned to judge correct height of the bottom of the ladder and identify any potential issues with the ladder or ropes once in place.

One common issue found is that the pilot ladder does not extend the required 2.0 m past the accommodation platform when a combination arrangement is used. Photo 2 illustrates an example of a pilot ladder not extending the required height past the platform.



Internet address for all current marine notices: www.amsa.gov.au

Page 2 of 11



Photo 2: Example of non-compliant combination pilot ladder arrangements.

As shown in photos 2 and 3 persons cannot climb the pilot ladder to a level where they can move safely onto the accommodation ladder.



Photo 3: Person unable to safely access accommodation ladder platform from pilot ladder.

Internet address for all current marine notices: www.amsa.gov.au

Page 3 of 11

Securing of Pilot Transfer Arrangements

The pilot ladder is normally secured at its thimble end with shackles. However, due to the varying freeboard at specific loading conditions, the pilot ladder cannot always be secured at full length by the thimble ends. Under such circumstances it must be secured at an intermediate length. That can only be done in a safe way by ensuring that the weight of the ladder is transferred from ladder's side ropes to the approved strong point on deck directly.

The ladder's steps, spreaders or chocks should not be used to carry the weight of the ladder as they are not designed for this and do not have sufficient strength. For this reason, shackles, bars and tongues should not be used to secure the ladder to the deck. They will damage the ladder and put weight on the parts which are not designed to carry the weight.

Photo 4 shows an example of an unsafe use of shackles to secure pilot ladders.




Photo 4: Unsafe pilot ladder securing arrangements (Reproduced with permission from Fremantle Ports).



Photo 5: Unsafe pilot ladder securing arrangements.

Internet address for all current marine notices: www.amsa.gov.au

Page 4 of 11

Photos 5 shows the pilot ladder being secured to the strong point by using a shackle passed through the pilot ladder side ropes. This puts increased load on the single part of the side rope and the chock securing arrangements.

It is common industry practice to use a rope stopper usually in the form of a rolling hitch knot between the pilot ladder sides ropes and the approved strong point on the main deck. This will transfer the weight of the ladder arrangement directly onto the designated strong point and will not damage the ladder.

It is suggested that two strong (at least 2 x 24 kN) manila ropes be used to secure the pilot ladder. Photo 6 illustrates a method of tying a rolling hitch knot.




Photo 6: The rolling hitch knot. (Reproduced with permission from Fremantle Ports).

Photo 7 provides an example of rolling hitch knots being used to secure pilot ladders to approved main deck strong points.



Photo 7: Rolling hitch knots being used to secure pilot ladders to approved main deck strong points (Reproduced with permission from Fremantle Ports).

Internet address for all current marine notices: www.amsa.gov.au

Page 5 of 11

Inspection and Maintenance

Ongoing inspection and maintenance of pilot boarding arrangements are an essential part of ensuring their continued safe operation. Paragraph 10.1 of Part A of the International Safety Management Code (ISM) requires ship operators establish procedures to ensure a ship is maintained in conformity with the relevant rules and regulations, including pilot transfer arrangements. Such procedures should include regular inspections of the pilot transfer arrangements and storage to prevent damage of such equipment when not in use.



Photo 8: Pilot ladder where side ropes parted when in use (Reproduced with permission of the MAIB).



Internet address for all current marine notices: www.amsa.gov.au

Page 6 of 11

Common areas of defects can be the thimble ends of the pilot ladder. Corroded end point thimbles as illustrated in photo 9, can damage the side ropes leading to failure.



Photo 9: Example of corroded end point thimbles (Reproduced with permission from Fremantle Ports).



Another common area is the frayed or damaged side ropes as illustrated in photo 10. These should be detected during routine visual inspections.

Photo 10: Frayed side rope.

Internet address for all current marine notices: www.amsa.gov.au

Page 7 of 11

If side ropes are frayed, or in any way degraded the ladder should not be used.

The man ropes which are used as part of the arrangements should also be regularly inspected. There have been two recent incidents of man ropes parting during transfer operations. Though rope type is not specified in SOLAS the Australasian Marine Pilots Institute recommends grade 1 manila be used. These should be tagged and included in onboard inspection and maintenance procedures. Good practice dictates these should be removed from service at the same intervals of not more than 30 months or sooner if required.

Trap door arrangements and use of combinations ladder

There has been an increase in ships fitted with trapdoor arrangements. The additional requirement for their use is "the pilot ladder and man ropes shall be rigged through the trapdoor extending above the platform to the height of the handrail".




Figure 1: Pilot card depicting trap door arrangements.

If the pilot ladder and man ropes are not rigged through the trapdoor this creates an unsafe arrangement for persons as illustrated in photo 11



Internet address for all current marine notices: www.amsa.gov.au

Page 8 of 11




Photo 11: Unsafe trapdoor pilot transfer arrangement.



Internet address for all current marine notices: www.amsa.gov.au

Page 9 of 11

Responsibility for safe pilot transfer arrangements

Responsibility for safe practices for personnel transfers rests with each person involved in the activity including the ship owners, operators, master and crew, pilotage providers, pilots and pilot boat crew, as well as the person being transferred. All parties should observe both the spirit and intent of the regulations, to ensure safety is not compromised.

Where a person suspects that the pilot transfer arrangement provided is unsafe, they should refuse to use the arrangement until it is made safe by the master and crew and report the circumstances to AMSA¹ and their employer. Where such situations occur, AMSA will endeavour to follow-up to determine the cause and actions taken. Where a ship is not calling into an Australian port, AMSA will follow up with the flag State.

When not in use, the pilot ladder and man ropes should be stowed appropriately to avoid exposure to contaminants or other elements that will degrade the ladder and man ropes. The ladder and man ropes should be regularly inspected by the ship's crew to ensure they remain ready for use.

Additional information

The <u>IMO/IMPA Pilot Ladder Poster</u> provides further guidance on pilot transfer arrangements This and other useful guidance material are available on the AMSA website and in the AMSA Pilot mobile App.

Implementation of standards

When conducting port State control (PSC) inspections, AMSA inspectors will pay particular attention to the material state of all equipment and the implementation of Marine Order 21, Res.A.1045(27) as amended by Res.A.1108(29), ISO 799-1:2019, MSC.1/Circ.1428 and MSC.1/Circ.1495/Rev.1. The relevant IMO circulars and resolutions can be obtained from AMSA or www.imo.org.

During recent PSC inspections AMSA surveyors have noted pilot ladders which have been constructed with splices in the side ropes.



Photo 12: Example of non-compliant pilot ladder with splices in side ropes.

¹ These should be reported using a incident alert (AMSA 18), report (AMSA 19) or marine safety concern. See <u>Incident reporting (amsa.gov.au)</u>

Internet address for all current marine notices: www.amsa.gov.au

Page 10 of 11

Pilot ladders constructed like this are considered non-compliant by AMSA. Ship operators and masters are recommended to check their pilot ladders for splices in the side ropes. It should be noted by operators coming to Australian ports that the availability of compliant pilot ladders is limited in Australia. To prevent avoidable delays operators are recommended to have spare compliant pilot transfer arrangements onboard.

Compliance with the referenced standards does not of itself assure safety in each case. A pilot transfer arrangement that complies with the standards but is incorrectly rigged still presents a hazard to anyone using the arrangement. Crew members assigned to rig a pilot transfer arrangement should be sufficiently familiar with the task. The master or responsible officer supervising the rigging of the pilot transfer arrangements should assess whether supplementary measures, such as lifejackets, harnesses, lifelines be made available to enhance the safety of personnel rigging the pilot transfer arrangement. Where a pilot transfer arrangement is rigged incorrectly, this may contribute to evidence that the master or crew are not familiar with essential shipboard procedures relating to the safety of the ship. A number of documents have been produced as referenced in this Marine Notice to assist in the rigging of a pilot transfer arrangement correctly.

Australian Maritime Safety Authority GPO Box 2181 CANBERRA ACT 2601



Internet address for all current marine notices: www.amsa.gov.au

Page 11 of 11

16.2 VTS Vessel Booking Application Form

Link to fillable PDF

consent, unless required to do so by law.

	Queens Governr						VTS	5	Vess	sel E	Bool	cing	Арр	olica	tion
hours before Telephone: Email: ships Vessel de	nust be comple e the ship's exp (07) 4839 0226 scheduler_glad tails (please	bected de stone@m	parture or r	emoval.	Scheduler n	o li	ater than 48 ho	our	s before	the ship				no later	than 24
Vessel name	e							_			— ř	NO num	ber		
Agent's com	nany name			Agent's	name					After ho	urs pho	one num	her		
been provid	o's Internationa ed to the Austr	alian Cust	toms Servic	e?	ails Secu 1	1	y level 2 3		Booking	applica	ation rer	marks			
	classified as b		-		Is th	is r	argo gas free?								
No 🔄 Yes	What type	e of cargo	will be carr	ied?	No		Yes								
LOA		Beam			Arrival disp		coment	D	WT			GRT			
LUA] Deam			Arrivat disp	pia	cement	Г	WI						
Main engine	power rating (kW)		Bow thr	uster power	rat	ting (kW)	L		Stern t	hruster	power r	ating (k	W)	
														,	
No Yes Master's full Vessel's last	erequired?	-	e Berthing dra	ft aft			Departure / Departure / Will a Pilot be No Yes Master's full i Vessel's dest	e re nar	Removequired?	val 🔲	of call	arture d	raft aft		
	int forward	— Ì	Jertining una	it ait		1	Departure dis	spl	acement	t					
Estimated	time of arriva	l - Fairwa	IV.			1									
Date		me		-			Requested	Pil	ot Boar	ding					
							Date	_		Time					
Requested Date	Pilot Boardin	ig me					Estimated ti	im	o of dor						
Dute				1			Estimated ti Date		e or dep	Time					
Requested	Port Entry														
Date		me		_			Will a helicop	ote	r or a lau	inch be	require	d to tran	sfer the	e pilot?	
							No 🗌 Yes		Helico	opter 📃	Laund	:h 🔲			
	pter or a launc			fer the p	ilot?		Will a tug/s b	oe r	required	?	Will lin	e boats	be requ	uired?	
No 📃 Yes	Helicopte	er 📃 Lau	inch 📃				No 🔄 Yes		Hown	nany?	No	Yes	How	v many?	
Will a tug/s	be required?	Will	line boats b	e require	ed?										
No 🔲 Yes	How man	y? No	Yes	How m	any?										
pilotage and to International C	ent: The Departme o meet obligations (Convention for the S officers and officers	under the Int afety of Life	ternational Shi at Sea (SOLAS)	p and Port F) 1974 Regu	acility (ISPF) Co lation XI-2/13 at	de. nd ti	This information is he Maritime Transp	req oort	uired by th and Offsho	ve Transpo pre Faciliti	ort Operati les Securit	ions (Marii ly Act 2003	ne Safety) (Cwith). I	Act 1994, Authorised	the

LTSR Forms Area Form F4330 CFD V01 Mar 2023

16.3 Dangerous Cargo Report (Form 3217)

Link to fillable PDF

a dit a	Print Form Reset Form
Queensland Government	Dangerous Cargo Report
Sections 90 and 91 of the Transport Operations (Marine Safety) Regulation 2016. Definitions • 'dangerous cargo' means any of the following cargoes, whether packaged, carried in bulk packagings or in bulk - (a) crude oil and petroleum products with a flash point not more than 60 degrees Celsius (b) dangerous goods (c) liquefied gases mentioned in the Codes for the Construction and Equipment of Ships Carrying Liquefied Gases in Bulk issued by the IMO (d) liquid chemicals mentioned in the Codes for the Construction and Equipment of Ships Carrying Dangerous Chemicals in Bulk issued by IMO and Annex II of MARPOL. • 'dangerous goods' means the goods mentioned in the	Is any part of the ship's cargo defined as 'dangerous goods' in the Definitions opposite? No Provide the following details: stowage, quantity, proper shipping name, UN number, IMDG classification and, where applicable, division, packaging group, flashpoint or flashpoint range (details may be provided on a separate sheet/s if necessary and attached to this form.)
International Maritime Dangerous Goods (IMDG) Code. • 'local marine service' means a shipping service where a ship is operated on Queensland intrastate voyages to	Name of person in charge of handling, stowing, loading or unloading of the dangerous goods
handle dangerous cargo.	Phone number Fax number
Please note	
following approved forms - • a properly completed Ship Information System (SIS) Booking Form (in ports where the SIS system is in use) provided the cargo details referred to below are forwarded to the Regional Harbour Master. • electronic communication (other than voice) of the information which is required on this form. Is this report for a local marine service? No ● Complete Section A only Yes ● Complete Section B overleaf only Section A Pilotage area or place for which the report is being made	Is any part of the ship's cargo defined as 'dangerous cargo' (other than 'dangerous goods') in the Definitions opposite? No Yes Provide the following details: stowage, quantity, proper shipping name, UN number, and, where applicable, flashpoint or flashpoint range (details may be provided on a separate sheet/s if necessary and attached to this form.)
Ship's name	Name of person in charge of loading, unloading or transfer of the dangerous cargo
	Phone number Fax number
Ship's IMO/Lloyd's number	
Agent's name and address	Is the dangerous cargo in good condition? No Provide details: (details may be provided on a separate sheet/s if necessary and attached to this form.)
Expected date and time of arrival	Yes 🗖
L / / : hrs Expected date and time of departure	Yes I declare that the information provided, to the best of my knowledge, is true and correct.
/ / : hrs	Agent/Owner/Master's name
Expected date and time of removal	
/ / : hrs	Agent/Owner/Master's signature Date
Expected date and time of transfer/loading of cargo	
/ / : hrs	Send to the Regional Harbour Master for the destination port/pilotage area

Dangerous Cargo Report continued ... (page 2 of 2)

Section B Location of local marine service Ship's name Ship's IMO/Lloyd's number Operator's name and address	Are there any passengers intended to be carried during the transport of the dangerous cargo? No Yes How many? I declare that the information provided, to the best of my knowledge, is true and correct. Agent/Owner/Master's name Agent/Owner/Master's signature Date I Send to the local Regional Harbour Master
Contact person's name Contact person's name Phone number Fax number Is this report for an initial voyage of a new local marine service? No Yes Expected date and time of commencement of voyage Is this report for subsequent voyage/s as part of a local marine service? No Is this report for subsequent voyage/s as part of a local marine service? No Yes Expected date and time of voyage/s (details may be provided on a separate sheet/s if necessary and attached to this form.) I / / I hrs	
Image:	Privacy Statement: Maritime Safety Queensland (MSQ) is collecting the information on this form as record of any dangerous cargo being carried by a ship into the Port. The information is collected pursuant to the <i>Transport Operations (Marine</i> Safety) Act 1994. Authorised officers within MSQ and the Department of Transport and Main Roads may have access to this information. The information recorded will not be disclosed to a third party without your consent or unless required by law.

Page 2 of 2 TRB Forms Area Form F3217 CFD V01 Oct 2016

16.4 Dangerous Cargo Event Report (Form 3220)

Link to fillable PDF

👬 🖉 Queensland	Dangerous Cargo Event Repor
Severnment Government	
Section 93 of the Transport Operations (Marine Safety) Regulation 2016.	Description of the event (if insufficient space, continue or separate sheet/s duly signed and attached to this form.)
Please note	
A dangerous cargo event report may also be provided in the following approved forms - • by radio or electronic communication giving the information which is required on this form.	
Ship's name	
Ship's IMO/Lloyd's number	
Particulars of person making report Owner Aaster Person in of ship of ship charge of place	Description of damage (if insufficient space, continue on separate sheet/s duly signed and attached to this form.)
Name and address of person making report	
Location of event	
Name of berth (if any)	
	Nature of injuries and/or fatalities (if insufficient space,
Date and time of event	continue on separate sheet/s duly signed and attached t
/ / : hrs	this form.)
Description of the dangerous cargo involved (if insufficient	
space, continue on separate sheet/s duly signed and attached to this form.)	
	I declare that the information provided, to the best of my knowledge, is true and correct.
	Signature Date
Privacy Statement: The Department of Transport and Main Roads is collecting the information on this form as a record of any dangerous cargo event that has happened at the place or on the ship. This information is required under the Transport Operations	
(Marine Safety) Regulation. Authorised departmental officers will have access to this information and your personal information will not be disclosed to any third party without your consent, unless required to do so by law.	Send to the Regional Harbour Master nearest the location of the event.

16.5 Arrival/Departure Report (Form 3452)

Link to fillable PDF

Print Form Reset For Queensland Government Please note: This report must be completed and lodged with the Regional H or no later than 24 hours before the ship's expected departure or removal. Interstate vessel Foreign going vessel N Port Date	Arrival/Departure Report
Click here to select port	Exempt
Vessel Details	Reason for exemption
Vessel name	Click here to select exemption reason
	or
Lloyd's number	Paid 🔲 at
	Payable From To
Has the ships' International Ship Security Certificate (ISSC) Number been provided to Australian Customs? Yes No Security level: 1 2 3 Gross registered tonnage Exempt master? Yes No	Certification By submitting this form electronically I/we warrant that the information provided is true and correct and I/we undertake to pay any port dues owing. Company name
Length overall (m)	Customer number (can be found on previously issued
	invoices)
Master's name	
Andred Details	Agent's name Phone
Arrival Details Arrival date Estimated Time	Address
Berth Previous port of call	Privacy Statement: Maritime Safety Queensland (MSQ) is collecting
Anticipated Removals To Wharf No. Date Departure Details	the information on this form as record of shipping movements, billing records for pilotage and to meet obligations under the International Ship and Port Facility Security Code (ISPS Code). The information is collected pursuant to the <i>Transport Operations (Marine Safety) Act</i> 1994, the <i>International Convention for Safety of Life at Sea (SOLAS)</i> 1974 <i>Regulation XI-21</i> 73 and the <i>Maritime Transport Act</i> 2003. Authorised officers within MSQ, the Department of Transport and Main Roads and Queensland Port Authorities may have access to this information. Your personal details will not be disclosed to a third party without your consent or unless required by law. Office Use Only The following information should accompany this form with any supporting documentation for archiving.
Departure date Estimated Time	Conservancy dues
	Pilotage inwards due
Berth	Pilotage outwards due
	Removal
Next port of call	Cancellations due
	Delay charges due
Special Conditions connected with arrival/removal/departure	Totals
	Sales Order Number
	Invoice Number Date
I	TBB Forms Area Form F3452 CED V01 Jan 2017

Important Notice Where the services of a Pilot are required

Provision of a Pilot

- Legislation requires that a person must not navigate a ship in a compulsory pilotage area unless the person uses the services of a pilot.
- 2. From 2 November 2013, changes to the Transport Operations (Marine Safety) Act passed the responsibility for the provision and delivery of port pilotage services for ports north of Brisbane (except Abbot Point) to the port government owned corporations. This is being achieved by giving port authorities the legal responsibility for the provision and delivery of pilotage services in designated Compulsory Pilotage Areas. The Responsible Pilotage Entities for all Compulsory Pilotage Areas are specified in Schedule 4 of the Transport Operations (Marine Safety) Regulation 2016 (TOMS Regulation), as follows:

Column 1	Column 2
Compulsory pilotage area	Responsible pilotage entity
Southport pilotage area	MSQ
Brisbane pilotage area	MSQ
Bundaberg pilotage area	Gladstone Ports Corporation
Gladstone pilotage area	Gladstone Ports Corporation
Rockhampton pilotage area	Gladstone Ports Corporation
Hay Point pilotage area	North Queensland Bulk Ports Corporation
Mackay pilotage area	North Queensland Bulk Ports Corporation
Abbot Point pilotage area	MSQ
Townsville pilotage area	Port of Townsville Limited
Lucinda pilotage area	Port of Townsville Limited
Mourilyan pilotage area	Far North Queensland Ports Corporation
Cairns pilotage area	Far North Queensland Ports Corporation
Cape Flattery pilotage area	Far North Queensland Ports Corporation
Skardon River pilotage area	Far North Queensland Ports Corporation
Thursday Island pilotage area	Far North Queensland Ports Corporation
Weipa pilotage area	Far North Queensland Ports Corporation
Karumba pilotage area	Far North Queensland Ports Corporation

*Note: The TOMS Regulation also rescinds the Bowen, Cooktown, Maryborough and Port Douglas as Compulsory Pilotage Areas however these areas remain as pilotage areas.

- MSQ has entered into an agreement with Port of Townsville Limited to deliver pilotage services in the Abbot Point Compulsory Pilotage Area.
- 4. The Responsible Pilotage Entity may provide services on the basis that:
 - the person to whom the services are provided accepts the risk of loss or damage caused by an act or omission by the Responsible Pilotage Entity and waives any right to claim against the Responsible Pilotage Entity in contract, tort or otherwise howsoever, for any loss or damage (including consequential loss) to any person or property which arises directly or indirectly out of the provision of the pilotage services
 - the Responsible Pilotage Entity is not obliged to provide or arrange for the provision of the pilotage services if circumstances beyond their control mean the services cannot reasonably be provided at the time requested or at all and no compensation will be payable in this event.


Circumstances beyond the control include, but are not limited to:

- industrial action by pilots, line boat operators or others
- inability to schedule a pilot at the time required
- any direction or regulation having the effect of prohibiting or preventing the carrying out of the pilotage
- a failure by a sub-contractor to carry out any part of the pilotage services.


The contents of this notice may be pleaded in any action or proceedings arising out of the provision of pilotage services.

TRB Forms Area Form F3452 CFD V01 Jan 2017


16.6 Bundaberg port layout







16.8 Pilot ladder boarding arrangement



16.9 Requirements for pilotage exemption

Requirements for the Issue of PilotageExemption for the Ports of Gladstone,Bundaberg and Port Alma

The following are the requirements for the issue of the above licences:

- The applicant must have completed six voyages as Master within the last 12 months
- The applicant must have completed two voyages at night (included in the above six voyages)

NOTE: A VOYAGE IS ONE TRIP IN AND ONE TRIP OUT

- The applicant must complete a written and if considered necessary, an oral examination
- The applicant must hold a current medical and eyesight certificate to Marine Orders Standards
- After completion of the examination the applicant must practically demonstrate his/her ability to
 handle a vessel in the Pilotage Area (this will be one voyage with a licensed pilot) of which one trip
 must be in the hours of darkness for a night endorsement.

Exemptions will be granted as follows:

- For bauxite vessels up to a maximum of 256m LOA not West of South Trees Wharf (Gladstone)
- For other vessels up to a maximum of 200m LOA (Gladstone)
- No exemptions will be granted for Clinton Coal Wharf (Gladstone)

Exemptions will be granted for various sizes of vessels as follows:

over 200m LOA - no exemptions other than for bauxite vessels to South Trees Wharf ONLY

The applicant will be required to complete two voyages as Master within the previous 12 months with a licensed pilot to have the exemption opened up for a larger size vessel or to extend his/her exemption to another area within a Pilotage Area. One of these voyages must be completed at night.

If the applicant has not used the exemption to a particular wharf within 6 months, they will be required to complete one voyage with a licensed pilot to that wharf for the exemption to be current for that wharf.

Use Within Pilotage Areas

A licence may be issued for a particular area within a Pilotage Area, provided that all recommendations set out herein governing the qualifications for and issuing of a licence are complied with.

Standard of Examinations

The standard of examination shall be similar to that required for a licensed pilot and shall include:

- Adequate knowledge of the Pilotage Area for which the certificate is required, and in particular of the surroundings, minimum keel clearances, tides and currents, buoys, beacons, lights and signals of or within that Pilotage Area of the approaches thereto
- Ability to satisfactorily complete blank charts of the said Pilotage Area marking thereon soundings and characteristics of the existing buoys, beacons, light, signals and other aids to navigation
- Adequate knowledge of the relevant Acts and regulations applicable to the Pilotage Area, in
 particular those relating to dangerous substances
- Thorough knowledge of control requirements in the Pilotage Area, traffic patterns, separation lanes and special signals, rules and communications relating thereto

Period of Validity and Requirements for Re-examination

Subject to the following conditions a, b, c and d below, a licence will be valid for a maximum period of two years from the dating of granting of such licence, and may from time to time be renewed for such period not exceeding two years as is appropriate.

Application for renewal shall be accompanied by evidence of visual and medical fitness and of the date of the last use of the licence. A period of grace for renewal not exceeding two months may be allowed in certain circumstances.

- (a) Where a Master has not used the licence within any period of six months, the licence shall become invalid and may only be re-validated after the Master has made one voyage with a Pilot
- (b) Where a Master has not used the licence within two years, the licence may be re-validated after the Master has made two voyages with a Pilot within a period of two months after expiration of the two year period and has passed and oral examination
- (c) Where a licence has not be re-validated with a period of two years and two months, the licence will be cancelled
- (d) A licence may be suspended by the Chief Executive where major port changes or developments are taking place

Record of Use of Licences

The responsibility for maintaining the validity of the licence is that of the Master, and to this end every Master shall be required to keep a true and correct record of the dates on which it has been used and where applicable, the area navigated within the Pilotage Area. The Master may be asked to produce this record when required.

As an exempt Master you will be required to:


- Comply with any rules, regulations and directions in force with respect to pilots and exempt masters
 of the port
- Obey and execute all lawful directions issued by the Regional Harbour Master
- Use utmost care and diligence in piloting any vessel of which you have pilotage charge
- Not attempt to undertake pilotage duties when, through illness or other circumstances, you
 consider yourself unable to perform those duties in a fit and proper manner.

Application and Renewal Checklist

Do you have:

- A copy of a current and valid Master's Licence
- Proof of completing training, appropriate to the port, in Radar and ARPA Simulation (Initial Issue)
- A valid Medical Certificate issued pursuant to Marine Orders 9 "Health-Medical Fitness"
- A valid Eyesight Certificate issued pursuant to Marine Orders 9 "Health-Medical Fitness"
- Two (2) color passport size photographs taken not more than 12 months from the date of the application. (Initial issue or replacement only)
- Completed Marine Application form (F1974)
- The original of an existing pilotage exemption (Renewal only)
- A current pilotage assessment report
 - > This is required for first issue of an exemption and area endorsement
 - Renewal of an area endorsement if the requirement of at lease one arrival and one departure for the pilotage area every six months has not been completed.
 - For the ongoing suitability of an exempt master.

16.10 Pilotage Passage Plan



PORT OF BUNDABERG

VESSEL :

Pilotage Plan	- Departure		/ Removal					
Dilot						Dilot Card		ŝ
							y ao	2
Date	ω	Standby @				Defects	yes	2
Passage					Π	TUG NAME	Bollard Pul	Position
Drafts h more	FWD		AFT					
Tide	Time	Ŧ	Height	Range	0			
					Γ	UKC Calculation	ation	
					Τ	Area		
					Τ	Depth		
						+ Tide		
Checklist : Departure / Removal	arture / Remova	_				Avail Depth		
Security Level	_	ő	ppler / G	Doppler / GPS / EM Log	8	- Draft		
Main Engine		С 2	Radars	•		SUKC		
Steering		D A	Aldis Lamp	••	a line	(Min	(Minimum UKC is 0.9m)	
D Thruster? kM	kw / BHP	86	onstrained	Constrained by draught	H W	The Maste	The Master and the Piot certify that	tify that
Whistle			Special Features?	fures?		and discus	the motece man has been agreed and discussed with the bridge team	e team.
						Date / Time		
Both anchors	Both anchors deared and ready for use?	for use?	~			Pilot		
_						Master		
Bundsberg Hatour Should any emergen	Bundaberg Harbour Control Istens continuously on VHF Ch 13 & 16. Should any emergency arise, call Bundaberg Harbour Control on VHF	ously on \	/HF Ch 13 /	<u> </u>	Depart	Departure Diagram	_	
 The bridge team must safety Queensland a 	Tori o for assessments. To the birdde hear munat monitor vessels position as required by Maritime Safety Queensiand and information al regulations.	tion as re stions.	quired by M	laritime				
Alterations Outbound	utbound							
Approx W/O position	tion		New Cra	Distance				
Clear of Oil or Sugar Wharf	ar Wharf		348° T	02				Ĩ
Bcn #20 transit with Bcn #22	h Ban #22		000° T	02				
Bcn #22 transit with Inner Reach FDIR	h Inner Reach FD#	œ	049° T	0.4'				μοι
Bon #18 transit with Middle Reach FDMR	h Middle Reach Fi	MR	072'T	90				ŧn.
Bcn #16 abeam			081° T	0.3'				
Bow approaching Bon #14	Bon #14		090° T	4.0				1
dum - handing Pangatha Vonesii Ontain 210	arte.							
				1				

PORT OF BUNDABERG

VESSEL :

Hild Hold Hold <th< th=""><th>Pilotage Plan</th><th>- lan -</th><th>Arrival</th><th></th><th></th><th></th><th></th><th></th><th></th><th></th></th<>	Pilotage Plan	- lan -	Arrival							
American Searebra Defects yess no 929	Pilot						Pilot Car	Þ	yes	2
TUG NAME Boiard Pull Position 16 AFT AFT Position 16 Height Range Height Position 10 Depth Nrea Nrea Position 1 Doppler / GPS / EM Log Depth Arrea 1 Doppler / GPS / EM Log Nreadens Nrea 1 Doppler / GPS / EM Log Nreadens Nreadens 1 Adds Lamp Avea Nreadens 1 Adds Lamp Nreadens SUKC 1 Adds Lamp Monimum URC is 0.5ml 1 Special Features? Direct 1 Constrained by draught The Masse and the Plot contribut 1 Constrained by draught The Masse and the Plot contribut 1 Constrained by draught The Masse and the Plot contribut 1 Constrained by draught The Masse and the Plot contribut 1 Constrained by draught The Masse and the Plot contribut 1 Doppler Direct Direct 1 Domonter The Masse and the Plot contribut Direct 1 Domonter Direct Direct 2 Contracted on VHE Arread flot plot cont Direct	Date		60	tendby @			Defects		yes	8
AFT AFT AFT 100 Height Range Height 100 Height Range UKC Calculation 100 Height Range UKC Calculation 100 Height Ariea Ariea 100 Elepth Hilde Hilde 100 Constrained by draught Avial Depth 100 Adds Lamp SUKC Sukc 100 Constrained by draught The Masse and the Plot Anal bein apoint 100 Constrained by draught The Masse and the Plot Control on Anal 100 Constrained by draught The Masse and the Plot Anal bein apoint 1000 Constrained by draught The Masser and the Plot Anal bein apoint 1000 Constrained by draught The Masser and the Plot Anal bein apoint 1000 Constrained by draught The Masser and the Plot Anal bein apoint 1000 Constrained by draught The Masser and the Plot Anal bein apoint 1000 Constrained by draught The Masser 1000 Constrained by draught The Masser and the Plot Anal bein apoint 1000 Constrained by draught The Masser 1000 Constrained by Diagram The Masser 1000 Constrained by Diagram <th>Passage</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th>TUG NAM</th> <th>\vdash</th> <th>Bollard Pull</th> <th>Position</th>	Passage						TUG NAM	\vdash	Bollard Pull	Position
Ite Height Range Image Height Range Image Height Range Image Depth Image Note Image Height Image Depth Image Note Image Note <	Drafts n more		ę		AFT			\square		
Image: Second state of the se	Tide	F	Time	Hei	aht	Range		•		
Area Area Image: Sector Sect		·					UKC Cal	culat	ion	
Image: Section of the section of t							Area	<u> </u> .		
Image: Section of the section of t							B	· -		
Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by draught - Draft - Draft Image: Section of the constrained by dramet - Draft - Draft Image: Section of the constrained by dramet - Draft - Draft Image: Section of the constrained by dramet - Draft - Draft Image: Section of the constrained by dramet - Draft - Draft Image: Section of the constrained by dramet - Draft - Draft Image: Section of the constrained by dramet - Draft -							+ Tide			
Image: Complex / GPS / EM Log - Draft Image: Complex / GPS / EM Log - Succ Image: Complex / GPS / Em Log Masker and the Photo emitty that Reven accelled that the Photo emitty for that Reven accelled that the Photo emitty of the Photo emit	Checklist:	Arrival					Avail Dep	÷		
Image: Constrained by draught BUKC Image: Constrained by draught Adds Lamp Adds Lamp Image: Constrained by draught Constrained by draught Adding Lamp Image: Constrained by draught Constrained by draught Adding Lamp Image: Constrained by draught Adding Lamp Adding Lamp Image: Constrained by draught Constrained by draught Adding Lamp Image: Constrained by draught Image: Constrained by draught Adding Lamp Image: Constrained by draught Image: Constrained by draught Adding Lamp Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Arrival Diagram Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Arrival Diagram Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Arrival Diagram Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by draught Image: Constrained by		Level			ppler / G	PS / EM Log				
Adds Lamp Adds Lamp Adds Lamp Adds Lamp Adds Lamp Adds Lamp Constrained by draught Constrained by draught The Muster end the Plot certify the Automotion on the constrained by draught Constrained by draught Constrained by draught The Automotion on the constrained by draught Constrained by draught The Automotion on the constrained by draught Constrained by draught The Automotion on the constrained by draught Constrained by draught The Automotion on the constrained by draught Braddon on the Contrained by Martime Dank / Time Renddon on the constront on VHE Arrival Diagram Renddon on the constront on VHE Dank / Time Renddon on the constront on VHE Arrival Diagram Renddon on the constront on the constrained by Martime Plot Renddon on the constront on VHE Arrival Diagram Constrained by Contrained Dank / Time Renddon on the constront on the constront on the constrained with the strained on the constrained on the constraine		gine			dars		SUKC			
Constrained by draught The Muster and the Plot certify that Charts. ECDS and publications Event publications Special Features? Part decuased with the folge term d ready for use? Date / Time Bindibern Harbour Corried on VHE Pilox Master Date / Time Ready for use? Pilox Second moustly on VHE Arrival Diagram Store Diamo Second screed on VHE Arrival Diagram Store 0.5 Secort 0.5 Secort 0.5 200*T 0.5 216*T 0.5 216*T 0.5 200*T 0.5 216*T 0.5 200*T 0.5					lis Lamp	The Part			Arm UNC is 0.9m)	
Image: Class of publications Image: Class of Class of Program Plan has been acreed with the bridge name. Image: Class of Clas			4		nstrainec	t by draught	N MAL	last last	and the Plot card	SAV THIS AND
Image: Special Features? and decursed with the bridge team d ready for use? Date / Time burdlenent Harbour Control on VHE Date / Time Burdlenent Harbour Control on VHE Arrival Diagram see poston as required by Martime Plick New Diamov T Stort 3.5 220°T 3.5 220°T 0.5 228°T 0.5 200°T 0.5 200°T 0.5					ats, ECDIS	8 and publicatio		lota de	Plan has been a	peareed
d ready for use? a continuent on VHE Ch 13 & 16. Bundabert Hintour Control on VHF Bundabert Hintour Control on VHF Bundabert Hintour Control on VHF Bundabert Hintour Control on VHF Bundabert Hintour Control on VHF Chain Control on Sugar Berth d b Oll or Sugar Berth Defection Defection Plicat Massel Plicat Massel Plicat Massel Massel Arrival Diagram Control on Sugar Berth Plicat Massel Arrival Diagram Plicat Massel Arrival Diagram Plicat Massel Arrival Diagram Control on Sugar Berth Plicat Plicat Plicat Massel Plicat Massel Arrival Diagram Plicat Massel Arrival Diagram Plicat Plicat Massel Plicat P					ecial Fea	tures?	and de	sousse	d with the bridge	team.
d ready for use? Plict Masker Burdanen Harbour Centrel on VHF Burdanen Harbour Centrel on Centrel on VHF Burdanen Harbour Centrel on Centrel							Date / 1	e.		
d to Oil or Sugar Berth		tions des	and ready	for use?			Master	'.'		
assets position as required by Maritime and ingulations. Can Distance 2011 3.5 2011 0.5 2021 0.5 2161 0.2 2161 0.2 2161 0.5 2161 0.5 216		arbour Cont nergen ov a	trol list ens confinu rise, call Bundab e	ousiv on V ra Harbou	HF Ch 13 r Control o	. L	rival Diagram			
New Diamos Cna Zaor 1 3.5 220°T 3.5 262°T 0.5 258°T 0.5 228°T 0.5 218°T 0.2 200°T 0.2 170°T 0.5 170°T 0.5		stance. In must mo	onitor vessels pos internation al regula	tion as rec	aried by A	Aartiime				
Mew Dietanoo 270°T 3.5 28°T 0.5 28°T 0.5 218°T 0.5 218°T 0.2 218°T 0.2 170°T 0.5 170°T 0.5	Alteration	s Inbo	pun							
270°T 3.5 261°T 0.6 252°T 0.5 228°T 0.5 218°T 0.5 218°T 0.5 200°T 0.2 170°T 0.3 170°T 0.3	Approx W/O	position	_		New Crs	Distance				
261*T 0.6 252*T 0.5 226*T 0.5 216*T 0.2 200*T 0.2 170*T 0.3 170*T 0.3	Entrance Bea	succe			270° T	3.5				
252°T 0.5 228°T 0.5 218°T 0.2 200°T 0.2 170°T 0.5 170°T 0.5	Bcn #12 clear				281° T	9.0				
236°T 0.5 216°T 0.2 200°T 0.2 170°T 0.3 170°T 0.3	Bow approac	hing Ban	#16		252° T	0.3				
218° T 200° T 170° T d to Oil or Sugar Berth	Sea Reach L	eads abe	am		707T	0.5				реции
200° T 170° T Ired to Oil or Sugar Berth	Bcn #20 trans	sit with B	an #22		218° T	2.0				
170° T ired to Oil or Sugar Berth	Bow approac	hing Ban	#22		200° T	2.0				
Courses as required to Oil or Sug ar Berth	Bow approac	hing Ban	#24		170° T	0.3'				
	Ö	Inses as	required to Oil	or Sugar	Berth					

16.11 Marine Pollution Report (Form 3968)

Link to fillable PDF

Queensland Government	Marine Pollution Re Email to: pollution@msq.q		EP)
Urgent Standard This form is used to record the initial detail address shown above.	Information only 🔲 s of a reported/sighted marine pollution spill	. The form is to be sent to	the email
Date of incident Time of incident Location of pollution Lat.	Long.	POLREP ID number Incident investigation Marine incident number Category	Yes No
Location Pollution source Ship Land	Unknown		
Ship type Recreational Commer Ship name	cial 🔲 Fishing 🔲 Trading ship Ship registratio		
Pollutant Sheen Diesel Bilge	HFO Other 🕞		
Extent Size of the slick (length and width in meter) Litre		
Report details Has the discharge stopped? Yes	No 🗌 Unknown 🔲		
Weather conditions (tide and wind) Photos taken Video taken Original report source	Samples taken 🔲 Sample taken by		
Statutory agency	Combat agency		
Initial response brief			
Sender details Name	Position		
Agency	Contact phone (mobile/office)	Fax number	
Signature	Date Time		
Telephone Maritime Safety Queensland: Brisbane: 07 3305 1700 Mackay: 07 49	56 3489 Gladstone: 07 4971 5200 To	wnsville: 1300 721 263	Cairps: 1300 551 889

TRB Forms Area Form F3988 CFD V01 Jul 2016

16.12 Marine Incident report (Form 3071)

Link to fillable PDF



Incident description

Marine Incident Report

Transport Operations (Marine Safety) Act 1994

This is the approved form to report a marine incident in Queensland. A ship's master must report a marine incident to a shipping inspector within 48 hours of the incident taking place, except in cases where the ship is lost or presumed lost in which case the incident must be reported by the ship's owner. If the initial report is not in the approved form a further report must be submitted using this form at the earliest opportunity. You should fill in all fields that are applicable. This form, and all supporting documents, should be returned to a Maritime Safety Queensland office, the Queensland Police Service or a Queensland Boating and Fisheries Patrol Office. Penalties apply for failing to report a marine incident.

Position of incident					
Date Time Body of water/Landmar	k				
/ / am pm					
Location	Latitude Longitude				
Inland waters (non-tidal) Smooth waters Partially	smooth waters Offshore				
Type of incident					
	Grounding: Other incident: unintentional person hit by propeller or ship intentional parasalling incident Onboard incident: parasalling incident diving incident diving incident crushing or pinching other onboard incident other onboard incident becked where the ship has disappeared and the location and circumstances is an economic write-off this should be check marked as 'Ship lost' below				
Incident Severity Rating Fatality Number of persons Number of persons	Ship lost ³ Damage to property only ⁴				
² Requiring admission to h	ospital ³ Economic write-off or not recovered ⁴ No damage to any ships				
Environmental conditions					
Weather	Visibility				
Clear Hazy Cloudy Rain Flood	Good Fair Poor				
Water conditions					
Calm Choppy Rough Very rough Strong current or tidal flow Swell height (metres)					
	ong current of tidal llow Swell height (metres)				
Wind speed	Construction and a now Swell neight (metres)				
Wind speed	ng (16-33kts) Gale (>33kts) Wind coming from				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron					
Wind speed Wind speed Uight (1-6kts) Moderate (7-15kts) Stron Ships involved					
Wind speed Wind speed Ught (1-6kts) Moderate (7-15kts) Stron Ships involved Number of ships involved Note: if more than two ships	ing (16-33kts) Gale (>33kts) Wind coming from				
Wind speed Wind speed Ught (1-6kts) Moderate (7-15kts) Stron Ships involved Number of ships involved Note: if more than two ships Own ship	eg (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page.				
Wind speed Wind speed Ught (1-6kts) Moderate (7-15kts) Stron Ships involved Number of ships involved Note: if more than two ships	ing (16-33kts) Gale (>33kts) Wind coming from				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Own ship Name of ship	were involved attach details on a separate page. Other ship Name of ship				
Wind speed Wind speed Ught (1-6kts) Moderate (7-15kts) Stron Ships involved Number of ships involved Note: if more than two ships Own ship	eg (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page.				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Own ship Name of ships Official registration number Registering authority	org (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registering authority				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Own ship Name of ship	were involved attach details on a separate page. Other ship Name of ship				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Own ship Note: if more than two ships Official registration number Registering authority Length (metres) Beam (metres) Year built	or (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Own ship Name of ships Official registration number Registering authority	org (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registering authority				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Own ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board	or to the ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stront Ships involved Note: if more than two ships Own ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board Number of passengers on board Number of crew on board Registration type Number of crew on board	g (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board Number of crew on board Registration type				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stront Ships involved Note: if more than two ships Own ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built	or to the ship Official registration number Registering authority Image:				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stront Ships involved Note: if more than two ships Own ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board Number of passengers on board Number of crew on board Registration type Number of crew on board	g (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board Number of crew on board Registration type				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stront Ships involved Note: if more than two ships Own ship Note: if more than two ships Official registration number Registering authority	g (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registration number Registration for the passengers on board Number of passengers on board Number of passenger Commercial passenger Commercial fishing Commercial non-passenger Commercial hire and drive Queensland Regulated ship				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stron Ships involved Note: if more than two ships Number of ships involved Note: if more than two ships Own ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board Number of crew on board Registration type Commercial passenger Commercial fishing Commercial non-passenger Commercial hire and drive Queensland Regulated ship Additional information for commercial vessels: Commercial vessels must also attach a copy of the passenger man Office use only Office use only	g (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registering authority Length (metres) Beam (metres) Year built Number of passengers on board Number of crew on board Registration type Commercial passenger Commercial fishing Commercial non-passenger Commercial hire and drive Queensland Regulated ship essels must attach master's and engineer's logs and commercial lifest.				
Wind speed None Light (1-6kts) Moderate (7-15kts) Stront Ships involved Note: if more than two ships Own ship Note: if more than two ships Official registration number Registering authority	g (16-33kts) Gale (>33kts) Wind coming from were involved attach details on a separate page. Other ship Name of ship Official registration number Registration number Registration for the passengers on board Number of passengers on board Number of passenger Commercial passenger Commercial fishing Commercial non-passenger Commercial hire and drive Queensland Regulated ship				

Ships involved - continued	
Own ship Ship description Motorboat PWC Sailing boat House boat Other (describe)	Other ship Ship description Motorboat PWC Sailing boat House boat Other (describe)
Engine Outboard Inboard (petrol) none Inboard/outboard Inboard (diesel) Other (describe)	Engine Outboard Inboard (petrol) none Inboard/outboard Inboard (diesel) Other (describe)
Number of engines Total engine power	Number of engines Total engine power
Hull material Steel Timber Ferro-cement Marine alloy Fibreglass/GRP Other (describe)	Hull material Steel Timber Ferro-cement Marine alloy Fibreglass/GRP Other (describe)
Damage to ship Ship lost Moderate damage (damaged but ship remains seaworthy) Major damage (ship unseaworthy) Minor damage No damage	Damage to ship Ship lost Moderate damage (damaged but ship remains seaworthy) Major damage (ship unseaworthy) Minor damage No damage
People involved	
Own ship Ship owner's details Owner's name	Other ship Ship owner's details Owner's name
Dedicated person ashore/operations manager (commercial only	Dedicated person ashore/operations manager (commercial only)
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	Address
Email address	Email address
Master's details Master's name	Master's details Master's name
Gender Date of birth Male Female / /	Gender Date of birth
Licence type and grade (for example, Master 5)	Licence type and grade (for example, Master 5)
Licence number Issuing authority	Licence number Issuing authority
Issue date Expiry date (if applicable)	Issue date Expiry date (if applicable)
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	Address
Email address	Email address
L	ontinued over page Page 2 of 4 TRB Forms Area Form F3071 CFD V01 Aug 2016

Persons involved - continued	
Own ship	Other ship
Watchkeeper/person at the helm	Watchkeeper/person at the helm
Role	Role
Crewmember Passenger Master (details as above)	Crewmember Passenger Master (details as above)
Name	Name
Gender Date of birth	Gender Date of birth
Male Female / /	Male Female / /
Licence type and grade (for example, Master 5)	Licence type and grade (for example, Master 5)
[]] [] [] [] [] [] [] [] [] [Cicence type and grade (for example, master 5)
Licence number Issuing authority	Licence number Issuing authority
Issue date Expiry date (if applicable)	Issue date Expiry date (if applicable)
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	Address
Email address	Email address
Witnesses	
Note: attach name and complete contact details of any witnesses to the in	cident on a separate page.
Deceased or injured person	
Note: if more than two people deceased or injured attach details on a sepa	arate page.
Name	Injury status
	Fatality Missing person Serious injury ⁵ Minor injury
Gender Date of birth	⁵ A serious injury is defined as one where the injured person was
Male Female / /	admitted to hospital.
Address	Nature of injury Name of hospital
	Activity of injured or deceased person
Telephone Which ship was this person associated with?	Person in charge (Master) Surfboard/surf-ski rider Person at helm Swimmer
Prepriorie Which ship was this person associated with:	Crew Para-flier
	Passenger on vessel Diver
	Water-skier Other
Descend on initial second	
Deceased or injured person Name	Injury status
	Patanty Comissing person Cosenous injury Conjury
Gender Date of birth	Nature of injury Name of hospital
Male Female / /	
Address	Activity of injured or deceased person
	Person in charge (Master) Surfboard/surf-ski rider
	Person at helm Swimmer
Telephone Which ship was this person associated with?	Crew Para-flier
	Passenger on vessel Diver Water-skier Other
Privacy Statement: The Department of Transport and Main Roads collects informat	
(Marine Safety) Act. This information may be released by the department to people to buy, sell, lease or insure the ship and, when relevant, litigants in matters about me	who have an interest that justifies access to the register, including people proposing
the registered owner, or Family Court matters. Your personal information will not be	anne incidents, or the insolvency, or external administration, or fraudulent activity of disclosed to other third parties without your consent unless authorised or required by
law.	
Co	ntinued over page Page 3 of 4 TRB Forms Area Form F3071 CFD V01 Aug 2016

Report details

A full description (including a diagram or chart extract) of the incident and events leading up to the incident are to be detailed in the space provided below (if insufficient space, please use separate pages, each extra page that is used is to be signed).

		 _	_	_	_		_	_	_	_	_	_	_		_	_	_	_	_	
Ņ																				
_																				
	_	 						-												
	_	 								 										-
	_																			
										 										-
	_	 						-												
																				-
	_																			-
	_				_	_				 _				_	_					

Owner's/Master's report ..

Assistance rendered/received at incident	
Name, status and phone number of person who assisted in completion of form (if applicable)	
Signature (Owner/Master) Date/	
Owner/Master name (please print)	Page 4 of 4 TRB Forma Area Form F3071 CFD V01 Aug 2016

16.13 Defects report form AMSA 355

Link to online form



REPORT OF SUSPECTED MARINE SAFETY CONCERN

Australian Government Australian Maritime Safety Authority

Please use this form to notify AMSA (reports@amsa.gov.au) of suspected safety concerns
 on vessels.

PART A: VESSEL INFORMATION

Vessel name						
IMO number	Unique identifier	Flag				
Master	Contact details					
Operator/Company name						
Responsible Person		Contact Number				
Domestic commercial vessel (Please tick if applicable)						
Class: 1 2 3 4	Operational Area : B Ext B B C					

PART B: INCIDENT DETAILS

Date	Time Local:	UTC:
Next port		
Location description	Lat	Long

PART C: CONTACT DETAILS

(Name and contact details will be treated by AMSA as being provided in confidence)

Name	Rank/Role
Contact details	Email address

PART D: BRIEF DESCRIPTION OF SAFETY CONCERNS/COMMENTS

AMSA 355 (12/17)

SV-HH

16.14 Gas-Free Status Declaration


Link to fillable form

Queensland Government	Gas Free Status Declaration					
Declaration required prior to acknowledgement of 'Gas Free' st	atus					
Master to declare						
Has your ship any flammable liquid or gas cargo on board in bu Yes No	lk?					
Have your empty cargo tanks been washed, vented and inspective Yes No	ted for flammable residue?					
Are your slop tank/s, pump room/s, and cargo pipe/s free of flar Yes $\hfill No$	mmable residue?					
Is your combustible gas indicator working and calibrated correct Yes No No	tly?					
Has the atmostphere in each pump room, cargo tank or residue and a zero reading obtained? Yes No						
Can the atmosphere in each pump room, cargo tank or residue Yes No	space be maintaned with a zero gas reading?					
Have you a current 'International Safety Guide for Oil Tankers a Yes No	and Terminals' (ISGOTT) manual on board?					
Master/Agent's Name Master/Agent's S	ignature Date					
	/ /					
Ship's Stamp						
Privacy Statement: The Department of Transport and Main Roads is collecting the inform Safety! Act 1994. The department may disclose this information to authorised department information will not be disclosed to a third party without your consent unless required or a	tal officers and officers of Queensland port authorities. Your personal					

Master/agent

To be lodged to the VTS centre at least 48 hours prior to ship's ETA pilotage area.

16.15 Bundaberg Port and Pilotage Areas



16.16 Example – Permission to Immobilise Main Engines


Link to fillable PDF

(THIS FORM IS ONLY TO BE USED IF THE REQUEST CANNOT BE SUBMITTED BY THE AGENT WITHIN <u>QSHIPS</u>)

a tist a		
Queensland Government	Permission to Immob Gladstone Region	oilise Main Engines -
This form is only to be used if t	he request cannot be submitted by	y the agent within QSHIPS.
To: RHM Gladstone Fax: 07 4971 5212 Email: vtsgladstone@msq.ql	d.gov.au	
Ship	Master	Berth
From On hrs / /	To On International Internatio	
Conditions on Issue		
1. Prior to immobilising, advise 'Gla		
 Moorings to be tended throughout During daylight hours, fly signal I 		
 On completion, advise 'Gladston 	-	
5. Master to ensure that the main e	ngines are capable of operating at full por	wer after immobilisation for arrival/
 departure manoeuvres. Estimated time to mobilise main 	angina in an amarganour	
hours	signe in an energency.	
	secutive days, approval is to be obtained	d to immobilise at the start of each day.
-		
Date submitted Signature: Mas	ter/Agent	
Approval by signature:		
Regional Harbour Master (Gladstone) Manager Vessel Traffic Manage	ement (Gladstone)
Distribution: Agent		
Distribution: Agent Gladstone VTS		


Privacy Statement: The Department of Transport and Main Roads is collecting the information on this form under the provisions of the Transport Operations (Marine Safety) Act 1994. The department may disclose this information to authorised departmental officers and officers of Queensland port authorities. Your personal information will not be disclosed to a third party without your consent unless required or authorised to do so by law.

TRB Forms Area Form F5198 CFD V01 Oct 2017



16.17 Small craft ship navigation areas and recommended courses

16.18 Cyclone tracking chartlet – eastern Australia



16.19 Pilot Ladder Checklist

Link to fillable PDF



Vessel name:

Date of pilot transfer

To the Master of the Vessel,

You and your crew are required to fully cooperate with the pilot launch crew to ensure the safe transfer of pilots to and from your vessel. You are responsible to ensure that the pilot ladder has been stored and maintained in good condition and that it is regularly inspected and certified by the manufacturer of the ladder that it complies with the requirements of SOLAS CHV- Regulation 23 - Pilot Transfer Arrangements Resolution A.1045 (27).

Maritime Safety Queensland supports all members of the pilot launch crew who decide not to transfer due to an unsafe ladder arrangement. Please note that any failure from you to provide a fully compliant pilot transfer arrangement will result in your vessel being rejected for pilot boarding, and additional charges may be levied to your vessel.

The Master of the Vessel is to ensure this Pilot Ladder Checklist has been completed and sent to the vessel's agent at least 72 hours prior to the planned pilot transfer taking place. The vessel's agent will enter the completed form into QSHIPS.

ltem	Checks to be performed	Yes	No
1.	Have all pilot ladders been kept clean, properly maintained, stowed and inspected at least 72 hours prior to arrival at the port to ensure that they are safe to use?		
2.	Are 'Certificates of Conformity' and 'Inspection Certificates' for pilot ladders maintained on-board the vessel?		
3.	Are manufacturer's plates clearly visible with matching certification for each ladder?		
4.	Are all pilot ladders only used for the embarkation and disembarkation of personnel?		
5.	Is there a copy of International Maritime Pilots Association 'required boarding arrangements for pilots' poster displayed on board?		
6.	Will the supervision of the rigging of the pilot ladder and of the pilot transfer arrangements be conducted by a responsible officer who has means of communication with the navigation bridge?		
7.	Will the vessel provide a person to escort the pilot by a safe route to and from the navigation bridge?		
8.	Will the pilot ladder and any operating mechanical equipment be tested prior to use?		
9.	Are there at least two people (including one Officer) on the ship, near the pilot boarding area to assist pilot's embarkation/disembarkation?		
10.	Are the ropes, heaving lines, splices and thimbles in good condition?		
11.	Are the steps, spreaders and chocks in good condition and free of any coatings?		
12.	Is the pilot ladder properly secured to the deck of ship?		
13.	Is the deck area where the pilot disembarks clean and free of obstructions?		
14.	Are the heaving line(s) in good condition and suitable for their intended use? Heaving line to be between 12-16mm diameter and fully inspected prior to use.		
15.	Are man ropes of at least 28mm and no more than 32mm in diameter and securely rigged?		
16.	Are the man ropes less than 24months old from the date of manufacture?		
17.	Have the manropes been in service for less than 12 months?		
18.	Is each pilot ladder less than 30 months old, or have they undergone the strength test as outlined in ISO 799-2019 with relevant certification?		
19.	Is the pilot ladder tied to a strongpoint on the ship, resting on the parallel body of the ship and are the steps horizontal?		

Page 1 of 4 LTSR Forms Area Form F5410 CFD V01 May 2024

Pilot Ladder Checklist continued page 2 of 2

20.	Is there an additional back-up pilot ladder available on board the vessel? (this is not a current requirement but is considered best practice)	
21.	Is the vessel capable and well-rehearsed in retrieving a man overboard?	
22.	Is there a lifebuoy and self-igniting light available at the pilot boarding area?	
23.	Is the boarding area adequately lit for pilot transfers at night?	

Vessel Master's name

Date

Vessel Master's signature

Hard copies of this document are considered uncontrolled. Please refer to the Maritime Safety Queensland website for the latest version. Port Procedures and Information for Shipping – Bundaberg, November 2024

Page 2 of 4 LTSR Forms Area Form F5410 CFD V01 May 2024


Rigging requirements for combination pilot ladders




Magnets must be 1.5 metres above combination ladder platform



One magnet for accommodation ladder




Manropes are to be tucked in line with the magnet/suction pad



The retrieval line is to be fastened above the last spreader step and is to lead forward without hindering or obstructing the pilot or pilot launch

Page 3 of 4 LTSR Forms Area Form F5410 CFD V01 May 2024



Page 4 of 4 LTSR Forms Area Form F5410 CFD V01 May 2024

16.20 Safe Work Method Statement – Boarding by ladder

Transport and Main Roads

Safe Work Method Statement for personnel transfers from launch to ship in the Gladstone Region

MSQ Region	Gladstone		Regional Harbour Master	+61 7 4971 5205 +61 459 827 398			
Relevant Legislation Standards and Code SWMS		Work Health and Safety Act 2011, Work Health and Safety Regulation 2011, Managing the risk of falls at workplaces Code of Practice (CoP) 2021, AMSA Marine Orders.					
Minimum number o	f employees	One (1)					
Description of activ	ity	Travel on a launch to the anchorage then boarding a ship whilst at anchor and disembarking from a ship to launch and returning to port.					
Related Documents		Vessel Safety Management System and boarding procedures					

Overview

All persons involved in this task must have the SWMS communicated to them prior to the work commencing (see signoff)

- This Safe Work Method Statement (SWMS) identifies generic hazards identified and associated with this particular type of work (see list identified hazards and risks below).
- · Other checklists, forms, training or procedures may be referenced in this document as controls for specific steps of the task being performed.
- This SWMS will need to be reviewed by the person supervising the activity to ensure it is specific to the work being performed, and any adjustments recorded on the daily prestart form for the day.
- The employee shall monitor the work to ensure this SWMS is being complied with and additional hazards are identified, controlled and recorded on the daily prestart for the day.
- If there are changes to the work being performed, that raises the risk level after controls are in place higher than what has been assessed, the employee must consider
 additional controls, or stop the activity covered by the SWMS.
- Where additional controls are implemented to address site specific risks, they must be documented in the site-specific SWMS section of the daily prestart and other workers
 involved in the task consulted in these changes.
- SWMS must be made available for inspection or review where the work is being undertaken, such as a hardcopy or be electronically accessible.

Indicate all the ap	propriate licences /	qualifications requir	ed to undertake th	e above-r	mentioned	high-r	isk construction	on activity	1.							
Role		Licence / Qualific	cation	Require	ed	F	Role			1	Licence / Qualification				Required	
All including pass	engers			No		N	Master of Ves	(Coxswain				Yes			
Crew Members		Elements of shipb (or higher qualifica Coxswain)		No		ļ	At least one cr	rew memt	ber	,	Applied first	t aid			Yes	
 Vessel SMS Vessel SMS Equipment Refer below 	Induction for a pass	ter and crew membe enger ertake this activ	ity safely:		this set											
		ve Equipment i	•			-										
This section is to ca	oture the additional F	PPE needed. It does no	ot include the Manda	tory PPE fo	or outdoor w	ork en	vironment) (refe	er to Other	Company	work prac	ctices/proced	dures).		<u> </u>		
			Z?Y	E.					ζ	1		9				
Eye protection must be worn:	Full face mask respiratory protectionmust be worn:	Half mask must be worn:	Hard hat must be worn:	Hearing protect must b worn:	ion		d protection t be worn:	AS 2210 complia footwea must be worn:	int ar	Protect body c must b worn:	lothing		protection be worn:	Life jao be wor	cket mus m:	
Y 🗆 N 🖂	Y 🗆 N 🖂	Y 🗆 N 🖂	Y 🛛 N 🗆	Υ□	N 🗵	Υ⊠	1 N 🗆	Υ⊠	N 🗆	Υ□	N 🖂	ΥD	N⊠	Υ⊠	N 🗆	
Glasses can be worn where required, secured with a lanyard.	Not with- standing any COVID-19 PPE requirements.	Not with- standing any COVID-19 PPE requirements.	Approved high visibility helmet (not hard hat) to be worn with chin strap secured.			rope Not	climbing a ladder. rubber per gloves.	Non-slip covered footwea be worn	t ar should							

Connecting Queensland

delivering transport for prosperity

2 of 9 9 13 QGov (13 74 68) www.tmr.qld.gov.au | www.qld.gov.au

	IDENTIFIED HAZARDS AND HIS		
Α	Falling in water from vessel/ship	J	Unfavourable weather
В	UV Radiation	к	Vessel propulsion failure
С	Workers not competent working at heights	L	Access Ladder in poor condition
D	Restricted movement when wearing equipment	М	Marine life (Sharks, Crocodiles, Irukandji or other identified marine life)
Е	Slippery structure slip, trip or fall	Ν	Struck by falling objects
F	Vessel ropes	0	Crushing injury between vessel and ladder
G	Vessel colliding with ladder/structure when working	Р	Isolation from medical assistance
н	Drowning	Q	Vessel Accident
	Manual handling		

IDENTIFIED HAZADDS AND DISKS FOD THIS HIGH DISK WORK

Preparation before activity commences

This SWMS requires the following tasks to be undertaken before the SWMS can be used.

Task	Controls	Responsible Officer
Check for inclement weather, sea state and vessel to be boarded.	 Weather/tidal information is to be reviewed Commencement of work to be assessed against forecasted weather conditions Daylight only transfer 	Vessel master
Conduct Daily Prestart	 Review controls within this SWMS Ensure all controls have been implemented before leaving berth Ensure all passengers/crew have been inducted onto the vessel 	Vessel master
Fitness for duty: Master/crew/passengers	 Not under the effects of medicinal drugs, illegal drugs or alcohol Master/crew/passenger not suffering from an injury or illness that may impact on this activity Not be suffering from fatigue Crew/passenger Identified by master as being capable of conducting work type 	Vessel master

Commence Activity

Ē	onimence Activity		Initial		Final	Monitor and Review / Res	ponsible Officer	
	Task	ldentified Hazards	Risk (without controls)	Implement Controls	Risk (with controls)	How control is monitored	Who is responsible	
1.	Boarding vessel for transfer	E, J, K, Q	Medium	 Persons boarding will act upon instructions from crew or master. Ensure 3 points of contact when boarding. All gear to be passed from the berth to the vessel crew for storage. Be aware of slips, trips and falls. Persons boarding to be aware of ropes. 	Low	 Inducted by trained crew and/or master of vessel. Induction training paperwork is completed and signed and placed in SMS. 	Vessel master or crew.	
2.	Generic induction to vessel	Fire, collision, grounding, muster stations, man overboard, flooding	Medium	Induction of personnel onto vessel.	Low	 Inducted by trained crew and/or master of vessel. Induction training paperwork is completed and signed and placed in SMS. 	Vessel master or crew.	
3.	Travel via vessel to ship to be boarded with crew/ passengers Crew/passengers competent for travel.	A-Q Sea sickness	High	 Vessel SMS MOB training to be provided. Undertake vessel SMS induction crew and passenger/s. Vessel crew advise access and egress of vessel. Follow instructions from vessel crew. Three points of contact while on board. 	Low	 Vessel Master ensures briefings are recorded in vessel log 	Vessel master or crew.	
4.	Approaching ship to be boarded (Assessment).	E,J,K,Q Sea sickness	High	 Vessel master to ensure all persons on vessel requiring transfer are ready for transfer. Master of vessel to make contact with the ship's Captain and determine the best lee of the ship and advise which section of the ship the transfer will take place. Master of the vessel to discuss the transfer of the persons with crew prior to engaging contact with the ship. 	Low	Vessel master	Vessel master	

Connecting Queensland

delivering transport for prosperity

9 13 QGov (13 74 68) www.tmr.qld.gov.au | www.qld.gov.au

4 of 9

Task	Identified	Initial Risk	Implement Controls	Final Risk	Monitor and Review / Res	ponsible Officer
Idək	Hazards	(without controls)		(with controls)	How control is monitored	Who is responsible
5. Climbing the vessel via boarding ladder	A-Q	High	 Passengers and crew to await master's confirmation prior to leaving the wheelhouse. Transfers are to be at the discretion of the vessel master in consultation with the ship's Captain, but generally should not be undertaken when at greater than Sea State 4 and a wind strength of 20 knots. Three points of contact at all times. Persons to ensure their lifejacket is worn correctly, is self-inflatable and within service Approved safety helmet is to be worn with chin strap attached. Ensure gloves are worn suitable for rope handling. Ensure laces on boots/shoes are tied correctly (where necessary). Vessel crew to be wearing an approved helmet with chin strap whilst transfer is taking place. Persons to follow instructions from vessel master and crew. Vessel to transfer persons on the side of ship that provides the best lee in consultation with the ship Master. The boarding ladder is to be lowered and secured by the ship's crew; an inspection will be conducted of the ladder at this time by the person boarding and the vessel crew. Should the ladder be determined unsuitable for climbing, the Captain of the ship is to be advised. If another ladder suitable to be used cannot be produced, the vessel is to return to port and advise VTS of this decision and why the transfer if in doubt stay on vessel, return to port and advise VTS of the decision. No equipment to be carried by any person boarding while climbing the ladder. Equipment will be passed up and down the ship in a bag by a heaving line. 		 Employee to cancel transfer if they do not feel safe, are uncertain, or as instructed by vessels master. Weather and sea state to be monitored by master of vessel. All persons to await instructions from vessel crew or master whilst on the vessel. 	Vessel master/crew/person boarding.

Connecting Queensland delivering transport for prosperity

5 of 9 9 13 QGov (13 74 68) www.tmr.qld.gov.au | www.qld.gov.au

Task	Identified	Initial Risk	Implement Controls	Final Risk	Monitor and Review / Res	sponsible Officer		
TASK	Hazards	(without controls)		(with controls)	How control is monitored	Who is responsible		
			 The master will manoeuvre the vessel to ensure the person boarding can grasp the boarding ladder. Wait for the vessel to manoeuvre into position and settle before stepping onto the ladder. Be aware of weather and sea state. Once the person has hold of the boarding ladder and is positioned on the ladder, the master will move the vessel away from the ship away from the ladder fall zone. The person should maintain three points of contact while climbing the ladder. The vessel is to remain close by in the event the person climbing should fall from the ladder. Should a person fall from the ladder. 					
6. On board ship after ladder climb	A-Q	High	 Ensure self-inflating lifejacket is worn and the approved helmet is worn. Remove helmet after boarding when safe to do so. The top of the Pilot ladder may involve an accommodation ladder (staircase with a handrail) to assist and trip hazards (trap doors). At top of ladder climb onto ship, following instructions by ship's crew. Maintain 3 points of contact at all times Person to advise master of transfer vessel by hand signal (thumbs up) or radio signal, whichever is appropriate once on board safely. 	Medium	Person transferred	Vessel master		
7. Disembarking from vessel	A-Q	High	 Ensure self-inflating lifejacket is worn. Approved safety helmet is to be worn. The top ladder may involve an accommodation ladder (staircase with a handrail) to assist. When descending the ladder, ensure any trip hazards are removed/person is aware of these hazards. Person to position themselves on the boarding ladder ready to disembark. Wait for vessel to settle alongside. Descend the ladder in a slow and safe manner. 	High	 Vessel crew to monitor descending person. Vessel crew to be aware of falling objects. 	Vessel master		

Connecting Queensland

delivering transport for prosperity

9 13 QGov (13 74 68) www.tmr.qld.gov.au | www.qld.gov.au

	Task	Identified	Initial Risk	Implement Controls	Final Risk	Monitor and Review / Res	ponsible Officer
	Task	Hazards	(without controls)		(with controls)	How control is monitored	Who is responsible
				 No person is to carry any equipment whilst descending the ladder. Vessel crew to ensure they are wearing an approved helmet with a chin strap during the transfer. Maintain 3 points of contact at all times. Vessel crew will monitor descent. Follow instructions of the vessels crew to time step off ladder. 			
8	. On board the vessel.	A-Q Sea sickness	High	 Once safely on board, person is to return to the vessel wheelhouse. Vessel crew to take hold of any gear being delivered back down from the ship by the heaving rope. Once all the persons and gear have been removed, the vessel is to manoeuvre safely away from the ship. Master to advise ship's Captain that all persons are present, and the vessel is returning to port. 	Medium	Crew to ensure all persons and gear on board before departure.	Vessel master
9	Disembarking the vessel when back at port.	E, J, K, Q	High	 All persons to wait in the wheelhouse of the vessel until the vessel has berthed. Await pilot crew or master's instructions to leave the vessel When leaving the vessel be aware of slips, trips and falls. Ensure three points of contact when disembarking the vessel. Vessel crew to pass any gear from vessel to person once the person has safely disembarked. 	Low	All persons on board including crew and master.	Vessel master.

Connecting Queensland delivering transport for prosperity 7 of 9 **13 QGov (13 74 68)** www.tmr.qld.gov.au | www.qld.gov.au Approved by Regional Harbour Master Gladstone

This document was created in consultation with the following:

John Fallon RHM Gladstone

Jennifer Tumbers ED WWM Gladstone

Leon McKenzie MO3

Date of consultation: / __/

SAFE WORK METHOD STATEMENT

Safe Work Method Statement has been discussed with the undersigned and the control measures to be followed have been understood.

Date	Name of worker Signature Date		Name of worker	Signature	

Connecting Queensland

delivering transport for prosperity

8 of 9 13 QGov (13 74 68) www.tmr.qld.gov.au | www.qld.gov.au

			Ris	k Matrix							Consequence		Likelihood
Risk Dimension	s	Rare	Unlikely	Likelihood Possible	Likely	Almo			Injury/illness requiring first aid treatment at most Insignificant Treatable health issues		Rare	May occur only in very exceptional circumstances. Frequency - Once in every 5 - 10 years	
Sever Majo Modera Mino O Insignifi	r ate r	HIGH MEDIUM LOW LOW	HIGH MEDIUM MEDIUM LOW	HIGH HIGH MEDIUM MEDIUM	EXTREME HIGH HIGH MEDIUM	EXTRE EXTRE HIG MEDI	ME H JM		2 N	linor	Reversible injury/ilness to one or more persons requiring medical treatment, but does not result in time lost or restricted duties. Unresolved minor health issues.	Unlikely	Could occur at some time but unlikely. Frequency - Once in 1 to 5 years.
X Insignificant LOW LOW MEDIUM MEDIUM ACTIONS TO BE TAKEN Extreme • unacceptable								3 N	Voderate	Moderate irreversible injury/illness to one or more persons. Reversible injury/illness to one or more persons resulting in time lost and/or restricted duties. Acute short term health issues.	Possible	Will probably occur in some circumstances. Once per month - year.	
High Risks • work must cease immediately, or not to be undertaken, until the risk is reduced • implement further control measures and/or obtain specialist advice. High Risks • immediate action required • risks to be reduced if possible • manager/supervisor authorisation required before work proceeds • ensure the work team is informed of the risk potential and control measures.									4 N	Major	Considerable irreversible injury/illness to one or more persons. Serious reversible injury/illness to one or more persons. Progressive chronic condition, serious health issues.	Likely	Will probably occur in most circumstances. Once per week - month.
Medium Risks Low Risks	:	authorisation by ensure the wor no additional ris work can proce	y the manager/s k team is inform sk control neces red	duce the risks where supervisor is required and of the risk potenti asary essment by workers.	al and control meas				5 5	ievere	 Fatality, or significant disabling injury/illness to one or more persons. Significant prolonged health issues. 	Almost certain	Is expected to occur in most circumstances. Once per day - week.
			Hierachy of cont										
First option - most effective: can the hazard be removed altogether by elimination of process or substance? Change the design of equipment, the workplace or the process													
2. Substitution involves replacing the hazard with one that presents a lower risk. Reduce or eliminate the exposure to a hazard by adherence to procedures, instructions, signage or training. Administrative controls are dependent on human behaviour for success.													
			3. Isolation	Separate yourself fron hazard from you.	the hazard or separ	rate the 6	PPE	8	and	the hazard	least effective: provides a barrier between a p d. This is dependent on PPE being chosen corre nd work at all times where required.		

Risk Matrix

Connecting Queensland delivering transport for prosperity 9 of 9 13 QGov (13 74 68) www.tmr.qld.gov.au | www.qld.gov.au