



NOTICE TO MARINERS

002 (T) of 2025

Issued by Mackay Maritime Region on 2 January 2025

Area: Whitsundays pilotage area
Locality: Mandalay Point Mooring Grid
Activity: Special Marker Buoy

Mariners are advised that:

A yellow Special Marker Buoy Fl.Y 2.5s has been positioned at Mandalay Point Mooring Grid in the approximate position Latitude 20° 16.028'S Longitude 148° 43.791'E. The buoy is to mark the location of a submerged vessel.

Mariners are advised to navigate the area with caution.

Refer to notice: none
Cancel notice: none

AUS charts affected: AUS252
ENC Cells affected: AU421148

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Mackay Regional Harbour Master's office:
Phone 07 4944 3700 Email: vtshaypoint@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Mackay) - Maritime Safety Queensland