

NOTICE TO MARINERS

399 of 2023

Issued by Mackay Maritime Region on 1 September 2023

Area: Whitsundays pilotage area
Locality: Pigeon Island
Activity: Aids to navigation established

Mariners are advised that:

three special mark buoys with light characteristics Fl Y 5s have been established in approximate positions:

- latitude 20° 15.641'S, longitude 148° 41.946'E
- latitude 20° 15.866'S, longitude 148° 41.910'E
- latitude 20° 16.064'S, longitude 148° 41.952'E

The buoys define a sensitive marine life area.

All mariners are advised to navigate with caution.

Refer to notice: none

Cancel notice: none

AUS charts affected: 252,253, 824

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Mackay Regional Harbour Master's office:

Phone 07 4944 3700

Email: vtshaypoint@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Mackay) - Maritime Safety Queensland