

# NOTICE TO MARINERS



## 309 of 2024

---

Issued by Brisbane Maritime Region on 20 June 2024

**Area:** Brisbane pilotage area  
**Locality:** Dunwich, Moreton Bay  
**Activity:** Aid to navigation re-established in position.

Mariners are advised that:

The Dunwich sand loading area beacon, a south cardinal beacon displaying the light characteristic VQ(6)+LFI(1)W 10s has been re-established in approximate position latitude 27°30.342'S, longitude 153°23.951'E to account for shoaling in the area.

Mariners should navigate with caution when transiting the area.

**Refer to notice:** none  
**Cancel notice:** none

**AUS charts affected:** AUS814  
**ENC Cells affected:** AU428153

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Brisbane Regional Harbour Master's office;

Phone: 07 3632 7500

Email: [vtsbrisbane@msq.qld.gov.au](mailto:vtsbrisbane@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Brisbane) - Maritime Safety Queensland