

NOTICE TO MARINERS



178 of 2024

Issued by Brisbane Maritime Region on 15 April 2024

Area: Brisbane pilotage area
Locality: Pelican banks reach, Brisbane River
Activity: Aid to navigation altered in position

Mariners are advised that:

The port lateral buoy with light characteristics Q.R in position latitude 27°23.4733'S, longitude 153°09.3523'E has been altered in position.

The new approximate position is latitude 27°23.495'S, longitude 153°09.349'E

Mariners should navigate the area with caution.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS237

ENC Cells affected: AU5BNE01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland