

NOTICE TO MARINERS



069 (T) of 2025

Issued by Townsville Maritime Region on 4 March 2025

Area: Abbot Point and Bowen pilotage areas

Locality: Port Denison, Bowen mooring area

Activity: Special mark buoy, reported unlit

Mariners are advised that:

Bowen mooring area special mark buoy Fl Y 2.5s in location latitude 20° 01.65' S and longitude 148° 15.76'E is reported unlit

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS268, AUS825

ENC Cells affected: AU320148

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland