

# NOTICE TO MARINERS



## 602 (T) of 2024

---

Issued by Gladstone Maritime Region on 16 December 2024

**Area:** Gladstone pilotage area  
**Locality:** South Channel  
**Activity:** Beacon S1 not in position

Mariners are advised that:

the starboard lateral mark beacon S1 previously located at position: 23° 53.922'S, 151° 30.395'E has been reported as missing. The beacon is no longer in its charted position and mariners are to navigate with extreme caution around this location.

**Refer to notice:** none  
**Cancel notice:** none

**AUS charts affected:** AUS246  
**ENC Cells affected:** AU5GLT01

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Gladstone Regional Harbour Master's office:  
Phone 07 4839 0208      Email: vtsgladstone@msq.qld.gov.au

**Notice authorised by:** Regional Harbour Master (Gladstone) - Maritime Safety Queensland