

# NOTICE TO MARINERS



## 090 (T) of 2025

---

Issued by Brisbane Maritime Region on 14 March 2025

**Area:** South East Queensland  
**Locality:** Canaipa Passage  
**Activity:** Damaged Navigational marker

Mariners are advised that:

A red lateral beacon has been damaged and is currently on its side in the Canaipa Passage, near position latitude 27° 42.172'S, longitude 153° 23.788E. The beacon may not be visible.

Mariners should navigate the area with caution.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** AUS814

**ENC Cells affected:** AU428153

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: [vtsbrisbane@msq.qld.gov.au](mailto:vtsbrisbane@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Brisbane) - Maritime Safety Queensland