



# Safety Certificate

## Light Vehicles (up to and including 4.5 tonne GVM)

Transport Operations (Road Use Management) Act 1995

### Owner and vehicle details

Vehicle Owner's name and address

JANE CITIZEN  
10 KOALA CRT  
BRISBANE

Postcode 4000

Plate number (if applicable) State

ZX12YT

Qld

VIN/Chassis Number

A B C D 1 2 3 4 A B C D 1 2 3 4 A

Make

HOLDEN

Model

COMMODORE

Body shape

SEDAN

Series (for example, EA)

VN

Badge (for example, Longreach Tradesman)

EXECUTIVE

Number of cylinders/rotors  
8

Fuel type (if gas, a current gas certificate is required for registration purposes)  
PETROL

No. of doors (incl. hatch)  
4

Engine Number (if applicable)

A B 1 2 C D 3 4 E F

### Compliance type

Compliance Plate

Import Plate

RAV entry

Other - give details

Compliance date

08 89

Vehicle colour

BLUE

Seating capacity

5

Left or right hand drive?

Left  Right

Tare (if applicable)

N/A

GVM (if applicable)

N/A

### Results of inspection- Please indicate

Pass  Fail

First inspection

Final inspection

Identification

Modifications

Seats and restraints

Lights and electrical components

Windscreen and windows

Body and chassis

Steering and suspension

Wheels and tyres

Brake components

Engines and drivelines

Exhaust emissions

Road test

Handbrake test

Service brake test- Peak

75 %

Peak %

Average 65 %

Average %

Distance 8 m

Distance m

Disclaimer - This inspection does not include a noise test and is not evidence the vehicle complies with statutory noise limits.

**Original (blue)** - This copy for registration of vehicle

**Duplicate (yellow)** - Purchaser's/ Owner's copy

**Triplicate (yellow)** - To be given to owner where a further inspection is required

**Quadruplicate (white)** - Book copy

## LV- A 012312 3

Details of items rejected

Mobile AIS unit - location of vehicle inspection

10 KOALA CRT  
BRISBANE QLD 4000

Mobile AIS unit - reason ICO was not used

OUT OF RANGE FOR DATA TO UPLOAD

Odometer reading

First inspection

Result

65487KM

Inspection date

28/12/23

Inspection time

07:30 am

Mobile AIS unit odometer reading

112434 KM

Signature of examiner

*[Signature]*

Examiner's no.

10101

Final inspection (must not be more than 14 days from date of first inspection)

Odometer reading

Result

Inspection date

/ /

Inspection time

: am/pm

Mobile AIS unit odometer reading

Signature of examiner

Inspection Station details: Name and location

SMITHY'S AUTO SERVICE

100 SECOND ST BRISBANE Postcode 4000

AIS number

0010

Mobile AIS unit registration number

12SA43

**Certification:** Approved Examiner - I have inspected the vehicle indicated on this form in strict accordance with the guidelines set out in the Queensland Light Vehicle Inspection Manual and have found no defect that would affect its safe use on the road and it meets the requirements of the Transport Operations (Road Use Management) Act.

Inspected by - signature of examiner

*[Signature]*

Date

28/12/23

Name of examiner (please print)

JOHN SMITH

Examiner's no.

10101

Proprietor - I have ensured that the requirements of the Transport Operations (Road Use Management) Act relating to the issue of this certificate have been complied with.

Issued by - signature of proprietor

*[Signature]*

Date

28/12/23

Name of proprietor

JOHN SMITH